

WEAR CONTAMINATION FLUID CONDITION

NORMAL ABNORMAL ABNORMAL



## MACK MR688S 140 Component Diocol Engine

Diesel Engine

Diesei Engine  DURALENE Dura-Max 15W40 (	52 QTS)						
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
TEOGRAMICATION	Sample Number		Client Info		DC0035874	DC0016300	DC0027566
We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.	Sample Date		Client Info		22 May 2024	13 Feb 2024	30 Mar 2023
	Machine Age	hrs	Client Info		31374	0	30321
	Oil Age	hrs	Client Info		0	0	30321
	Filter Age	hrs	Client Info		0	0	30321
	Oil Changed		Client Info		N/A	N/A	Changed
	Filter Changed		Client Info		N/A	N/A	Changed
	Sample Status				ABNORMAL	NORMAL	ABNORMAL
WEAR	Iron	ppm	ASTM D5185m	>120	11	4	11
	Chromium	ppm	ASTM D5185m	>20	0	0	0
All component wear rates are normal.	Nickel	ppm	ASTM D5185m		0	0	0
	Titanium	ppm	ASTM D5185m		0	0	0
	Silver	ppm	ASTM D5185m		0	0	0
	Aluminum	ppm	ASTM D5185m	>20	<1	<1	<1
	Lead	ppm	ASTM D5185m	>40	0	<1	<1
	Copper	ppm	ASTM D5185m	>330	3	<1	2
	Tin	ppm	ASTM D5185m	>15	0	0	0
	Vanadium	ppm	ASTM D5185m		0	0	0
	White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
CONTAMINATION	Silicon	ppm	ASTM D5185m	>25	3	3	4
There is a moderate amount of fuel present in the oil. Tests confirm the presence of fuel in the oil.	Potassium	ppm	ASTM D5185m	>20	1	0	<1
	Fuel	%	ASTM D3524	>3.0	<b>4.1</b>	1.1	<b>△</b> 5.1
	Water		WC Method	>0.2	NEG	NEG	NEG
	Glycol		WC Method		NEG	NEG	NEG
	Soot %	%	*ASTM D7844	>4	0.3	0.1	0.2
	Nitration	Abs/cm	*ASTM D7624	>20	8.1	5.4	7.6
	Sulfation	Abs/.1mm	*ASTM D7415	>30	19.0	15.4	18.8
	Silt	scalar	*Visual	NONE	NONE	NONE	NONE
	Debris	scalar	*Visual	NONE	NONE	NONE	NONE
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
	Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
	Odor	scalar	*Visual	NORML	NORML	NORML	NORML NEG
<u></u>	Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
FLUID CONDITION	Sodium	ppm	ASTM D5185m		2	0	1
The BN result indicates that there is suitable alkalinity remaining in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.	Boron	ppm	ASTM D5185m		6	4	2
	Barium	ppm	ASTM D5185m		0	0	0
	Molybdenum	ppm	ASTM D5185m		5	4	3
	Manganese	ppm	ASTM D5185m		<1	0	<1
	Magnesium	ppm	ASTM D5185m		71	63	57
	Calcium	ppm	ASTM D5185m		2326	2024	2309
	Phosphorus	ppm	ASTM D5185m		890	804	856
	Zinc Sulfur	ppm	ASTM D5185m		1056	1043	1052
		ppm Abe/1mm	ASTM D5185m	> 2F	4095	3441	3921
	Oxidation	AUS/.IIIIII	*ASTM D7414	>20	11.1	9.2	11.4

Base Number (BN) mg KOH/g ASTM D2896

ASTM D445

Visc @ 100°C cSt

9.01


13.2

7.61

12.2

7.84

**12.3** 







Report Id: BRULAU [WUSCAR] 06238008 (Generated: 07/18/2024 11:04:24) Rev: 1

Laboratory Sample No. Unique Number : 11126842

Lab Number : 06238008

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : DC0035874

Received **Tested** 

: 16 Jul 2024 : 18 Jul 2024 Diagnosed

: 18 Jul 2024 - Wes Davis

**BLANCHET CONCRETE PUMPING** 9585 LYNN BUFF CT

LAUREL, MD US 20723 Contact: ED BAILEY

F: (301)206-4470

Test Package : MOB 2 ( Additional Tests: FuelDilution, PercentFuel ) Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

EBAILEY@PUMPCONCRETE.COM T: (301)708-1159

Contact/Location: ED BAILEY - BRULAU