



[DAIBER A-54-C/94-B-16] STABILIZER REBOILER

Customer: PTRHTF20194

KANATA ENERGY GROUP DAIBER GAS PLANT A-54-C/94-B-16 FORT ST. JOHN, BC V1J 0H8 Canada

Attn: Jason Carew Tel: (250)261-9197

E-Mail: jason.carew@kanataenergy.com

System Information

System Volume: 5580 ltr

Bulk Operating Temp: 293F / 145C

Heating Source:

Blanket:

Fluid: PETRO CANADA PETRO-THERM

Make: ALCO GAS & OIL

Sample Information

Lab No: 02298380 Analyst: Clinton Buhler Sample Date: 07/21/19 Received Date: 07/22/19 Completed: 07/30/19


Recommendation: *** Diagnostician`s Note: This sample is mostly water. Suggest the client drain off the water from the reservoir, then take a more representative sample. ***An immediate re-sample is required!Excess water in system. Please note that the fluid's acidity and viscosity is excessive and may not be representative. Please re-sample immediately. Please draw sample from most representative area of the heater vessel as possible. First drain all free water from system. Follow this by a purge of at least 20 liters of fluid until the fluid coming out is hot per normal operating temperatures. Collect sample and submit to the lab for analysis and Petro-Canada Technical Services will review and provide recommendations


Comments: Water contamination levels are severely high. Water contamination levels are severely high. ppm Water contamination levels are severely high. Acid Number (AN) is severely high. Visc @ 40°C is severely high.





Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]





Historical Comments sample results indicate that the fluid is suitable for continued service. However, the reduced flash point, and slightly increased GCD % < 335°C can be indications of thermal degradation (cracking of the fluid molecules creating light ends). To help bring the flash point closer to new spec, perform a venting regime of the expansion tank. During venting, turn off the blanket gas to allow the light end vapors to escape. Re-sample in 6 months. Please ensure sample point is from a fluid zone most representative of system condition and that a thorough purge precedes the sample. COC Flash Point is abnormally low.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.