

## **WANSON EPC 2500 ES**

## Customer: PTRHTF40020

LE DUC FINE FOOD BV MEESTER SNIJDERWEG 18

**ZUID-HOLLAND** 

STELLENDAM, ZUI NETHERLANDS

Attn: Wilbert Snijers

Tel:

E-Mail: w.snijers@klt.nl

System Information

System Volume: 1500 ltr

Bulk Operating Temp: 265F / 129C

Heating Source:

Blanket:

Fluid: PETRO CANADA PURITY FG HEAT TRANSFER FLUID

Make: WANSON

Sample Information


Lab No: 02309761 Analyst: Philip Riley Sample Date: 09/13/19 Received Date: 09/19/19


Completed: 11/05/19


Recommendation: Was this an oil change? All parameters around Flash Point and viscosity seem to have recovered to normal levels, but the insoluble are very high. Try some filtration to remove insoluble matter and check at normal oil sample interval.

Comments: Pentane Insolubles levels are severely high.












Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]



Historical Comments	
04/16/19	COC Flash Point trending downwards, and must show caution. If it can be recovered safely through any form of venting (although no great volume of light molecules look to be present) if would be worth doing to potentially extend the life of the fluid. Iron ppm levels are noted. COC Flash Point is abnormally low.
09/28/18	Looks to have been changed from previous sample. COC Flash Point already low and if safe to do so recommend venting system if possible to remove light molecules that have potentially brought flash point down. All other parameters within allowable limits. COC Flash Point is abnormally low.
08/30/18	COC Flash Point is very low indeed. Viscosity is trending slightly downwards also. Recommend the fluid is changed COC Flash Point is severely low.
01/31/18	COC Flash Point significantly lower than expected, confirming also previous result. Looking at the GCD the system has potentially been vented, there look to be fewer light end molecules. This has however had no impact on the COC Flash Point. All other parameters look to be improved from previous result. As this is a repeat result of the previous flash point, primary recommendation is for a system change out including a flush COC Flash Point is severely low.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.