



[PROCESS HEATER PLTS 1 & 2 / LSD: 3-22-78-12W6] CL#1604-0442-02 BIRCHCLIFF

Customer: PTRHTF20039

BRENNTAG CANADA INC 3124-54TH AVENUE SE CALGARY, AB T2C 0A8 CA

Attn: Matthew Kryska

Tel:

E-Mail: mkryska@brenntag.ca

System Information

System Volume: 19733 ltr

Bulk Operating Temp: 356F / 180C

Heating Source:

Blanket:

Fluid: PETRO CANADA PETRO-THERM

Make: Petro-Tech

Sample Information


Lab No: 02331379 Analyst: Clinton Buhler Sample Date: 12/01/19 Received Date: 01/13/20 Completed: 01/15/20


Clinton Buhler

Clinton.Buhler@HFSinclair.com

Recommendation: Sample results indicate that the fluid may be suitable for continued service. However, % boil-off of 16.52% and reduced 10% and 90% distillation temperatures is significant and may be an indication of thermal degradation, contaminants such as condensate or possibly a result of high blanket gas pressure. It is recommended to routinely vent off any low boiling vapors from the system on a regular basis. This may need to occur during an outage in the event the high blanket gas pressure is required for positive suction head pressure. Please re-sample fluid in 6 months after thorough venting has been performed.

Comments:






Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]

0

Baseline Data



Historical Comments	
09/19/18	Sample results indicate that the fluid is suitable for continued service. % boil-off of 2.03% and slightly reduced flashpoint may be an indication of thermal degradation or possibly a mixture of fluids. As a good preventative maintenance practice, it is ideal to vent off any low boiling vapors from the system on a regular basis.Re-sample fluid in 6 months to establish a trend
04/01/16	The flash point on this sample is extremely low as is the Viscosity. Check for leakage of condensate into heat transfer system. COC Flash Point is severely low.
	Flash point of samples is extremely low. Possibly contaminated with condensate. This would also be the reason the viscosity is so low versus new oil. COC Flash Point is severely low.
06/19/15	Flash point is still severly low although not as low as previous sample. GCD's have also improved. Resample again in 6 months. COC Flash Point is severely low.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.