

[KEYERA BRAZEAU RIVER GAS PLANT / 3-12-46-14W5] HOT OIL SYSTEM PLT 1

Customer: PTRHTF30084

Keyera Partnership Brazeau River Ga...

Box 7318

Drayton Valley, AB T7A 1S5 Canada

Attn: Ken Bouchard Tel: (780)894-3601

E-Mail: ken bouchard@keyera.com

System Information

System Volume: 14000 ltr

Bulk Operating Temp: 446F / 230C

Heating Source:

Blanket:

Fluid: PETRO CANADA PETRO-THERM

Make: IAP HEATER

Sample Information

Lab No: 02364496


Analyst: Kevin McDermott Sample Date: 07/05/20 Received Date: 07/14/20

Completed: 08/04/20 Kevin McDermott

kevin.mcdermott@petrocanadalsp.com

Recommendation: Fluid remains in good condition overall with very little change from the previous sample in Nov 2019. The viscosity is slightly low and the flash point is really low. Given the history these low values are likely from a previous exchanger leak.

Comments: COC Flash Point is severely low.






Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]

11/13/19

10/03/19

06/29/18

08/10/17



Nice to see absence of water that we saw in the Oct 30 sample. Must have been a bad sample. Suggest submitting annual samples - sooner if fluid gets exposed to stressed condition or exchange leak is suspected. Water content seen in previous sample is resolved. Flash point is very low, GCD 10% & viscosity also low. Likely from previous thermal cracking and/or exchanger leak. However these valve are all very similar to sample from July 2018.

Some level of thermal cracking has occurred over time but no additional degradation since the June 2018 sample. There is significant amount of water present in the fluid sample. Water contamination can sometimes be from a poorly purged sample point. Suggest to submit another sample ensuring a thorough purge of

the fluid sample. Water contamination can sometimes be from a poorly purged sample point. Suggest to submit another sample ensuring a thorough purge of sample point. (GCD) 10% Distillation Point is abnormally low. (GCD) % < 335°C is marginally high. COC Flash Point is marginally low.

The very low flash point, decrease in viscosity and increasing GCD<335 indicate that thermal cracking is occurring. Suggest venting off light ends from fluid. Also

make sure there is adequate circulation to prevent further thermal degradation. COC Flash Point is severely low. (GCD) % < 335°C is marginally high. (GCD) 10% Distillation Point is marginally low.

Fluid remains in very good condition. Very little change from the June 2015 sample. Suggest annual sample submission to proactively monitor fluid condition.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.