




[KEYERA PARTNERSHIP / 3-12-46-14W5] PLANT 2


Customer: PTRHTF30084	System Information	Sample Information
Keyera Partnership Brazeau River Ga... Box 7318 Drayton Valley, AB T7A 1S5 Canada Attn: Don Renner Tel: (780)894-3601 E-Mail: don_renner@keyera.com	System Volume: 14000 ltr Bulk Operating Temp: 455F / 235C Heating Source: Blanket: Fluid: PETRO CANADA PETRO-THERM Make: PETROTHERM ENG.	Lab No: 02378568 Analyst: Kevin McDermott Sample Date: 09/22/20 Received Date: 09/29/20 Completed: 09/30/20 Kevin McDermott kevin.mcdermott@petrocanadalsp.com

Recommendation: Fluid remains in good condition overall with very little change from the previous sample in July 2020. Viscosity is slightly low and the flash point is really low. Given the history of this system these lower values are likely from a previous exchanger leak. Flash point can be increased by venting the surge tank head space or partial fluid changeout. Continue to submit annual samples to proactively monitor fluid condition.

Comments: COC Flash Point is severely low.




Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/g	%wt	°F/°C	°F/°C	°F/°C	%
09/22/20	09/29/20	0y	Slip stream filter	268 / 131	33.5	25.9	0.02	0.092	681 / 361	805 / 430	906 / 486	6.49
07/05/20	07/14/20	5y		241 / 116	245.8	26.1	0.07	0.030	691 / 366	808 / 431	906 / 486	5.62
11/13/19	11/20/19	0y	PUMP DISCHARGE	221 / 105	67.0	26.6	0.033	0.085	649 / 343	782 / 417	886 / 474	8.27
10/03/19	10/30/19	9y	TANK	248 / 120	70.2	21.9	0.026	0.052	681 / 361	797 / 425	897 / 481	4.97
06/28/18	07/10/18	0y	MAIN PUMP	219 / 104	37.9	26.7	0.02	0.016	700 / 371	806 / 430	904 / 484	3.23
Baseline Data				433 / 223		34.2	0.03		720 / 382	817 / 436	900 / 482	1.00





Sample Date	Iron	Chromium	Nickel	Aluminum	Copper	Lead	Tin	Cadmium	Silver	Vanadium	Silicon	Sodium	Potassium	Titanium	Molybdenum	Antimony	Manganese	Lithium	Boron	Magnesium	Calcium	Barium	Phosphorus	Zinc
09/22/20	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
07/05/20	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11/13/19	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10/03/19	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
06/28/18	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Baseline Data			0	0						0			0	0				0					0	

Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]



Historical Comments	
07/05/20	Fluid remains in good condition overall. The viscosity is slightly low and the flash point is really low. Given the history of this system, these lower values are likely from a previous exchanger leak. Continue to submit annual samples to proactively monitor fluid condition. COC Flash Point is severely low.
11/13/19	The very low flash point combined with low viscosity are symptoms of thermal cracking, but given the history of this system likely from a prior exchanger leak. Fortunately these low values are not significantly worsening since previous sample. Suggest submitting annual samples or sooner if fluid becomes stressed or if exchanger leak is suspected.
10/03/19	The reduced viscosity and severely reduced flash point suggest an exchanger leak since the previous sample June 2018. Suggest taking another sample to see if FP / visc are continuing to drop. COC Flash Point is severely low. Visc @ 40°C is abnormally low.
06/28/18	Flash point is very low, viscosity slightly lower, both caused by dilution from blanket gas, or early signs of thermal cracking. Suggest venting off light ends from fluid. COC Flash Point is severely low.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.