

MAIN HOT OIL SYSTEM

Customer: PTRHTF10068

Certainteed - Saint Gobain 1077 PLEASANT ST

NORWOOD, MA 02062 USA Attn: David Fletcher

Tel: (781)551-0656 E-Mail: david.r.fletcher@saint-

gobain.com

System Volume: 5000 gal

Bulk Operating Temp: 560F / 293C

System Information

Heating Source:

Blanket:

Fluid: PETRO CANADA CALFLO AF

Make: A.M.KINNEY

Sample Information

Lab No: 02401204 Analyst: Doug Vrooman Sample Date: 01/27/21 Received Date: 02/02/21 Completed: 02/05/21


Doug Vrooman


douglas.vrooman@hollyfrontier.com


Recommendation: The Main Hot Oil System sample results show a slight increase in Flash Point - 186 to 188, however, Acid number had a slight increase also from .07 to .10. GCD at 10% remains good at 363.0 as well the GCD 90% at 482.5. No Vanadium was detected. Continue to monitor by sampling at a routine basis.

Comments: COC Flash Point is marginally low.












Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]



It appears the rented unit to strip off low boilers has helped bring the flash point and viscosity higher. This might help limp along for a while. let's keep monitoring every 6 months and re-evaluate the best way to maintain the fluid moving forward (sweetening or rent the unit). Many customers run with low oil levels in the expansion tank. If your expansion tank is <75% full when in operation, best practices suggest that it should be, so fresh oil could be added to keep with best practices but also to help maintain the oil properties. (GCD) 90% Distillation Point is marginally high. COC Flash Point is marginally high. COC Flash Point is how at 174 degrees. GCD 90% has risen to 485.4. Recommendations are consistent with the previous sample recommendation. Continue with the plan in place to remove low boilers and/or sweeten the system with fresh fluid. COC Flash Point is abnormally low. (GCD) 90% Distillation Point is marginally high. The oil condition has deteriorated but the flow issues with the pump have been resolved. Thermal cracking has occurred, reducing the viscosity and the flash point. Blends of in-service oil are being prepared with fresh Calflo AF to find the proper sweetening ratio. COC Flash Point is severely low. Although slightly different due to pulling samples in different locations, the last two samples - 10/17/2019 confirm the results of the sample on 9/20/2019. We would still recommend venting off the low boilers and/or add fresh fluid to the system to change the COC Flash Point and (GCD) %. (GCD) 10% Distillation Point is abnormally low. (GCD) % < 335°C is marginally high. COC Flash Point is marginally low.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.