

FILLER HEATER

Customer: PTRHTF10068

Certainteed - Saint Gobain 1077 PLEASANT ST NORWOOD, MA 02062 USA

Attn: Carol Turgeon Tel: (781)278-0463

E-Mail: carol.turgeon@saint-gobain.com

System Information

System Volume: 2200 gal

Bulk Operating Temp: 550F / 288C

Heating Source:

Blanket:

Fluid: PETRO CANADA CALFLO AF Make: PERFORMANCE HEATING

Sample Information


Lab No: 02401205 Analyst: Doug Vrooman Sample Date: 01/27/21 Received Date: 02/02/21 Completed: 02/05/21

Doug Vrooman

douglas.vrooman@hollyfrontier.com

Recommendation: The sample results for the Filler Heater have shown slight improvements with Flash point from 188 to 190. Low boilers GCD 10% 363.4 have shown a slight increase whereas GCD 90% 483.7 have decrease slightly. Acid number has also increased from .05 to .09. Continue to monitor at planned intervals.


Comments: COC Flash Point is marginally low.



Report ID: [02401205] (Generated: 03/02/2021 15:43:38) - Page 1 - Copyright 2021 Wearcheck Inc. All Rights Reserved.



Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]



This new Higher Temp system continues to effect HTF condition. We are noticing that the viscosity has dropped to 24.0 cSt @ 40C as well as COC Flash point which has dropped to 188. We recommend Venting (boil-off), as soon as possible. We would also recommend venting more frequently and adding fresh (make-up) fluid more frequently to assist with fluid condition. There is no asphalt contamination reported at this time. COC Flash Point is marginally low. The sample results for the Filler Heater have shown slight improvements with Flash point from 175 to 198. Low boilers GCD 10% 362.9 as well as GCD 90% 483.8 have decrease slightly. Acid number has also decrease from .116 to .06. Continue to monitor at planned intervals. This new Higher Temp system is effecting HTF condition. We are noticing that the viscosity has dropped to 27.8 cSt @ 40C as well as COC Flash point which has dropped to 175. We recommend Venting (boil-off), as soon as possible. We would also recommend venting more frequently and adding fresh (make-up) fluid more frequently to assist with fluid condition. There is no asphalt contamination reported at this time. (GCD) 90% Distillation Point is abnormally high. COC Flash Point is abnormally low. We understand there was some issue with the nitrogen blanket on this new system hence the slight rise in Acid Number. Other properties look normal. Resample in 6 months to closely monitor this new system.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.