



Recommendation: Sample results indicate that the fluid is in suitable condition for continued service. Please re-sample in 12 months.

Comments:

Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/ g	%wt	°F/°C	°F/°C	°F/°C	%
06/02/21	06/08/21	24.0m	discharge pump	421 / 216	15.6	33.8	0.02	0.042	712 / 378	798 / 426	904 / 485	1.97
05/23/21	06/08/21	24.0m	Condy line heater	403 / 206	17.1	33.8	0.02	0.062	709 / 376	804 / 429	897 / 481	2.81
02/23/21	03/05/21	24.0m	off pump	424 / 218	9.1	32.7	0.02	0.044	725 / 385	814 / 435	915 / 490	1.25
10/12/18	10/19/18	37.0m		284 / 140	2.5	26.8	0.35	0.035	714 / 379	801 / 427	899 / 482	1.48
02/28/18	03/12/18	28.0m		396 / 202	45.8	31.6	0.01	0.042	724 / 385	820 / 438	911 / 489	1.46



Jun2/2



Historical Comments

05/23/21	Sample results indicate that the fluid is in suitable condition for continued service. Please re-sample in 12 months.
02/23/21	Sample results indicate that the fluid is in suitable condition for continued service. Please re-sample in 12 months
10/12/18	It is understood that there was recently a condensate leak into the HTF system. This may explain the reduced flash point. A reduced flash point can be a safety concern. Following all safety protocol, venting of the low boiling vapors will help restore the flashpoint level to acceptable levels. Blanket gas cannot be in service during venting. Investigate if blanket gas pressure of 210 kpa is required for circulating pump suction head. If so, further investigated is a concerned with service service of a concerned with service service service of a concerned with service serv
02/28/18	Sample results indicate that the fluid is suitable for continued service and has improved since last sample as both water and total Acid Number have reduced significantly. The percentage boil off <335C has increased from 0.75 to 1.46 and there has been a slight reduction in flash point. This can indicate possible thermal degradation or contamination. Consider regular venting of the expansion tank after which time the blanket gas is turned back on. Re-sample in 6-12 months.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.