



Recommendation: Sample collected at an improper location and possibly a contaminated container. Keyera has collected a new sample waiting on results.

Comments: Potassium ppm levels are severely high. Water contamination levels are severely high. ppm Water contamination levels are severely high. Pentane Insolubles levels are abnormally high. Sodium ppm levels are severely high. Boron ppm levels are abnormally high.

| Sample Date | Received Date | Fluid Age | Sample Location | Flash Point (COC) | Water (KF) | Viscosity (40°C) | Acid Number | Solids | GCD 10% | GCD 50% | GCD 90% | GCD % < 335°C |
|-------------|---------------|-----------|--------------------|-------------------|------------|------------------|--------------|--------|-----------|-----------|-----------|---------------|
| | mm/dd/yy | | | °F/°C | ppm | cSt | mg/KOH/ g | %wt | °F/°C | °F/°C | °F/°C | % |
| 09/02/21 | 09/20/21 | 14.0y | | 432 / 222 | 1255.2 | 32.5 | 0.03 | 0.408 | 707 / 375 | 806 / 430 | 900 / 482 | 1.70 |
| 09/22/20 | 09/29/20 | 0.0y | Slip stream filter | 268 / 131 | 33.5 | 25.9 | 0.02 | 0.092 | 681 / 361 | 805 / 430 | 906 / 486 | 6.49 |
| 07/05/20 | 07/14/20 | 5.0y | | 241 / 116 | 245.8 | 26.1 | 0.07 | 0.030 | 691 / 366 | 808 / 431 | 906 / 486 | 5.62 |
| 11/13/19 | 11/20/19 | 0.0y | PUMP DISCHARGE | 221 / 105 | 67.0 | 26.6 | 0.033 | 0.085 | 649 / 343 | 782 / 417 | 886 / 474 | 8.27 |
| 10/03/19 | 10/30/19 | 9.0y | TANK | 248 / 120 | 70.2 | 21.9 | 0.026 | 0.052 | 681 / 361 | 797 / 425 | 897 / 481 | 4.97 |







Historical Comments

| 09/22/20 | Fluid remains in good condition overall with very little change from the previous sample in July 2020. Viscosity is slightly low and the flash point is really low. Given the history of this system these lower values are likely from a previous exchanger leak. Flash point can be increased by venting the surge tank head space or partial fluid changeout. Continue to submit annual samples to proactively monitor fluid condition. COC Flash Point is severely low. |
|----------|---|
| 07/05/20 | Fluid remains in good condition overall. The viscosity is slightly low and the flash point is really low. Given the history of this system, these lower values are likely from a previous exchanger leak. Continue to submit annual samples to proactively monitor fluid condition. COC Flash Point is severely low. |
| 11/13/19 | The very low flash point combined with low viscosity are symptoms of thermal cracking, but given the history of this system likely from a prior exchanger leak. Fortunately these low valves are not significantly worsening since previous sample. Suggest submitting annual samples or sooner if fluid becomes stressed or if exchanger leak is suspected. |
| 10/03/19 | The reduced viscosity and severely reduced flash point suggest an exchanger leak since the previous sample June 2018. Suggest taking another sample to see if FP / visc are continuing to drop. COC Flash Point is severely low. Visc @ 40°C is abnormally low. |
| | |

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.