



Customer: PTRHTF30154	System Information	Sample Information
Panolam Surface Systems	System Volume: 60480 ltr	Lab No: 02451713
61 Domtar Road	Bulk Operating Temp: 509F / 265C	Analyst: Adam Koscielak
Huntsville, ON P1H 2J7 Canada	Heating Source:	Sample Date: 10/14/21
Attn: MIKE GODDEN	Blanket:	Received Date: 10/22/21
Tel: (705)789-9683	Fluid: PETRO CANADA CALFLO AF	Completed: 11/01/21
E-Mail: mike_godden@panolam.com	Make: GEKA	Adam Koscielak
		adam.koscielak@hollyfrontier.com

Recommendation: Sample indicates the presence of low boilers. GCD%<335°C was measured at 6.22%. Typical is 2.5%. Low Boilers can be reduced by following the heat transfer system manufacturers procedure for venting of the expansion tank. The higher % of low boilers has reduced the flash point to 178°C versus a typical of 224°C. Viscosity has also been reduced to 25.3 cSt@40°C from the typical of 32.3 for Calflo AF. GCD%@90% indicates some cracking of the fluid.Solids remain low at 0.047%.Next steps to consider:1 - venting of the low boilers, following heat transfer system manufacturers recommended procedure.2 - Sweeting the system by replacing approx 10% of the volume of the system, to help bring the viscosity and flash point up. However this should be done after the low boilers have been vented. Sample fluid after low boilers have been vented. Sample system before the planned change out in 2022.

Comments: COC Flash Point is abnormally low.

Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/ g	%wt	°F/°C	°F/°C	°F/°C	%
10/14/21	10/22/21	16.0y		352 / 178	87.4	25.3	0.17	0.047	671 / 355	790 / 421	904 / 484	6.22
08/19/20	08/26/20	6.0y	THERMAL OIL BUILDING	349 / 176	193.2	23.5	0.14	0.046	667 / 353	789 / 421	902 / 483	6.83





08/19/20
lower viscosity oil added to this system. at this stage, the low flash point is not a safety concern, but you need to monitor it. The system also does not show any acid formation and pipe corrosion. Please resample after 6 months. COC Flash Point is abnormally low.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.