


TFS H/O SYSTEM #2

Customer: PTRHTF10176	System Information	Sample Information
CERTAINTEED ROOFING	System Volume: 3738 gal	Lab No: 02493696
100 CERTAINTEED DR	Bulk Operating Temp: 525F / 274C	Analyst: Neil Buchanan
JONESBURG, MO 63351 USA	Heating Source:	Sample Date: 05/26/22
Attn: Jeff Montgomery	Blanket:	Received Date: 06/09/22
Tel: (952)261-9532	Fluid: PETRO CANADA CALFLO AF	Completed: 06/13/22
E-Mail: jeffrey.d.montgomery@saint-	Make: FSE	Neil Buchanan
gobain.com		neil.buchanan@hollyfrontier.com


Recommendation: Flash Point is severely low and GCD shows the formation of some light boilers. Other properties are acceptable.

Comments: COC Flash Point is severely low.

Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/ g	%wt	°F/°C	°F/°C	°F/°C	%
05/26/22	06/09/22	0.0m		280 / 138	0.00	23.7	0.06	0.059	663 / 351	791 / 422	901 / 483	7.10
01/04/22	01/13/22	0.0m		392 / 200	15.8	26.5	0.10	0.089	670 / 355	792 / 422	902 / 483	6.27
08/30/21	09/07/21	48.0m	MAIN PUMP STRAINER	342 / 172	11.0	23.8	0.09	0.079	659 / 348	791 / 422	904 / 484	7.55
10/08/20	10/15/20	48.0m	SIDE STREAM	284 / 140	15.8	24.7	0.13	0.084	668 / 353	792 / 422	903 / 484	6.66
01/07/20	09/17/20	48.0m	Strainer	345 / 174	14.2	27.0	0.21	0.149	679 / 359	794 / 423	901 / 483	5.17







Response (pA) 8 000

6,000

4,000

2,000

0

Historical Co

Low Boilers (%)

2

Bas

Mar15/17

Feb16/18

Jan8/19

Jan7/20

Aug30/21

Mav26/22

Thistorical Comments			
01/04/22	Sample looks good and is fit for further service. Resample next interval.		
	COC Flash Point is abnormally low. GCD indicates the formation of some low boiling hydrocarbons. Systems should be safely vented. COC Flash Point is abnormally low.		
	Viscosity is decreasing and light ends are increasing. Flash point is also getting in to critical area. We suggest planning on venting in the next couple of months to reduce light ends and raise viscosity and flash points. Resample after maintenance. COC Flash Point is severely low.		
	Sample was submitted 9 months after taking. Flash point is lower than normal but slightly higher than past sample. Low boilers are rising as well, if system can be vented (may have been already) it should be done. Timely sample submissions yield more relevant data. COC Flash Point is abnormally low.		

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.