

## **AUTOLIV BOILER #3**

### Customer: PTRHTF30004

AUTOLIV CANADA 20 AUTOLIV DRIVE P.O. BOX 1090

TILBURY, ON NOP 2L0 Canada

Attn: Jill Stevenson Tel: (519)682-1083

E-Mail:

#### **System Information**

System Volume: 4000 ltr

Bulk Operating Temp: 518F / 270C

Heating Source:

Blanket:

Fluid: PETRO CANADA CALFLO AF

Make: VAPOUR POWER

#### Sample Information


Lab No: 02544412 Analyst: Yen Garcia Sample Date: 03/02/23 Received Date: 03/10/23 Completed: 03/22/23


Yen Garcia

yen.garcia@HFSinclair.com

Recommendation: This is a second sample from the same system to confirm the January 24, 2023, results. The system was drained, cleaned, flushed and refilled with Calflo AF on 3/22/2023.

Comments: (GCD) 10% Distillation Point is severely low. COC Flash Point is severely low. Visc @ 40°C is severely low. (GCD) % < 335°C is abnormally high.








Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]

01/24/23

04/25/17

01/05/15

03/15/14



# 

Viscosity of the Calflo AF has been reduced. Possible cracking of the fluid has occurred, or another product has been added. Percent of boilers <335°C is quite high @ 13.90% and 10% point has been reduced to 313.5°C from a typical of 365°C. Flash point has been reduced to 148°C from the normal typical of 21°C. Consider venting system to reduce light boilers. Consider bleeding off some fluid and sweetening with Calflo AF to increase viscosity of fluid. Sulphur and Phosphorus additive levels are not consistent with Calflo AF. Confirm that Calflo AF is being used and topped up. Resample at 3 months after venting to confirm if low boilers have been reduced. Consider bleeding off some fluid and sweetening with Calflo AF is increase flash point and reduced by boilers. (GCD) 10% Distillation Point is severely low. COC Flash Point is severely low. (GCD) % < 335°C is abnormally high.

There is an indication of thermal cracking as the oil seems to have abnormall high light ends. If it is possible to vent the light ends out of the system through the expansion tank, then I would suggest that this be done. I would suggest that we re-sample the oil in this unit. The results are similar to the sample from 1/15/2014 (GCD) 10% Distillation Point is severely low. COC Flash Point is severely low. (GCD) % < 335°C is abnormally high.

There is an indication of thermal cracking as the oil seems to have abnormall high light ends. If it is possible to vent the light ends out of the system through the expansion tank, then I would suggest that this be done. I would suggest that we re-sample the oil in this unit (GCD) 10% Distillation Point is severely low. (GCD) % < 335°C is abnormally high. COC Flash Point is abnormally low.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.