




Recommendation: Sample results indicate the fluid is in suitable condition for continued service. The fluid's flash point has improved since the last sample in 2020. Please re-sample in 12 months.

Comments:

Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/ g	%wt	°F/°C	°F/°C	°F/°C	%
04/24/23	05/09/23	0.0y		381 / 194	29.8	29.7	0.08	0.044	717 / 380	814 / 434	909 / 487	2.82
10/20/20	10/28/20	11.0y	Pump discharge	266 / 130	36.6	28.4	0.01	0.092	713 / 378	811 / 433	900 / 482	3.46
03/25/20	04/02/20	0.0y	PUMP DISCHARGE	187 / 86	31.1	28.3	0.02	0.118	719 / 382	815 / 435	907 / 486	2.39
01/30/20	02/06/20	0.0y	PUMP SEAL	248 / 120	25.7	28.2	0.029	0.057	736 / 391	808 / 431	888 / 475	8.28
07/09/19	07/12/19	0.0y		259 / 126	66.5	27.8	0.037	0.026	708 / 375	805 / 430	898 / 481	3.43







Historical Comments

10/20/20	Sample results indicate that the fluid is suitable for continues service. Please note that the fluid's flash point has improved since the previous sample, yet the low boiling vapor content has increased. The flash point is still low. It is advised to continue regular venting of low boiling vapors to improve the fluids flash point. Resample in 6 months once venting regime has been initiated.
03/25/20	This is the re-run of the sample taken on March 25th when a low boiler vapor content of 15.8% was reported due to a GC fault. After GC repair the low boiler vapor content is 2.39%. The other parameters remain the same. The fluid is in a reasonable condition and suitable for further use. Venting is still important to try and increase the Flash Point of the fluid. COC Flash Point is severely low.
01/30/20	The fluid is in reasonable condition and suitable for further use. Viscosity is slightly low. Flash Point is very low. This is the result of a low boiler vapor content of 8.28% which is considered high. A Flash Point below 150 degrees C is a safety concern and the low boiler vapor content at this level may result in pump cavitation, flow problems or pump seal leakage. Venting of low boiler vapor to atmosphere is recommended. Please re-sample in 6 months. COC Flash Point is severely low. (GCD) % < 335°C is marginally high.
07/09/19	The fluid is in the same condition as the sample taken on the 4th of June. Flash Point has improved with an increase from 82C to 126C. This is still low and we have to keep in mind that the test method for Flash Point has low repeatability/reproducibility. Flash Points below 150C are considered a safety concern. Please keep venting on a regular basis. Considering a switch to N2 blanket gas is strongly advised. COC Flash Point is severely low.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.