


NEW - WANSON 450


Customer: PTRHTF40052	System Information	Sample Information
ROYAAN BV	System Volume: 800 ltr	Lab No: 02566012
HOGE MAAT 8	Bulk Operating Temp: 255F / 124C	Analyst: Bill Quesnel CLS,OMA II,MLA-
WIJK BIJ BUURSTEDE 3961 NC	Heating Source:	III,LLA-I
WIJK BIJ DUURSTEDE, 3961NC	Blanket:	Sample Date: 06/16/23
Netherlands	Fluid: PETRO CANADA PURITY FG HEAT TRANSFER FLUID	Received Date: 06/22/23
Attn: WILBERT SNIJERS	Make: WANSON	Completed: 07/07/23
Tel:		Bill Quesnel CLS,OMA II,MLA-III,LLA-I

Recommendation: We recommend that you vent the expansion tank to remove low boilers which assists in restoring the flash point of the fluid. We recommend an early resample to monitor this condition. No other corrective action is recommended at this time.

Comments: COC Flash Point is abnormally low.

Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/ g	%wt	°F/°C	°F/°C	°F/°C	%
06/16/23	06/22/23	16.8y		352 / 178	5.2	29.1	0.75	0.064	681 / 361	809 / 432	907 / 486	6.14
05/24/22	05/30/22	15.8y		378 / 192	33.6	29.1	0.63	0.068	685 / 363	810 / 432	910 / 488	5.64
01/22/21	01/28/21	14.0y		374 / 190	23.0	30.9	0.52	0.115	688 / 364	810 / 432	906 / 485	5.12
09/10/19	09/19/19	12.5y		329 / 165	31.5	25.4	0.625	0.029	699 / 371	819 / 437	909 / 487	4.16
12/16/16	01/27/17	10.0y		381 / 194	66.1	32.7	0.65	0.237	709 / 376	813 / 434	898 / 481	1.90





	Comment	

05/24/22	Oil condition is very stable and oil is fit for further use. Please sent in next sample at the next service interval.
01/22/21	Fluid fit for furhter use. Send in new sample at next service interval. COC Flash Point is slightly low.
09/10/19	COC Flash Point severely low and unless can be recovered (safely) through next sample period an oil change is recommended COC Flash Point is severely low.
12/16/16	The oil appears to be in good condition at this time. However there has been a spike in Iron levels which can have an adverse effect on stability in the short term moving forward. Suggest locating the source of Iron contamination. Iron ppm levels are abnormal.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.