



Recommendation: Sample results indicate the fluid is in suitable condition for continued service. Solids content has increased to 0.441% from 0.259% which can be associated with fluid degradation and/or contamination in the system. 90% GCD temperature is up slightly and viscosity has slowly trended up over the last several years. Acid Number is basically flat but still above new. Combined, these may point towards low levels of fluid oxidation. Please re-sample in 6 months and ensure expansion tank blanket gas remains functional. (carefully purge sample valve before drawing sample).

Comments:


Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/ g	%wt	°F/°C	°F/°C	°F/°C	%
02/08/24	03/01/24	0.0m		446 / 230	16	35.8	0.22	0.441	712/378	809 / 432	924 / 495	1.86
01/18/23	01/26/23	120.0m	heat loop	441 / 227	16.9	34.8	0.29	0.259	711 / 377	812 / 434	912 / 489	3.12
12/06/21	03/10/22	8.0m	expansion tank	417 / 214	14.3	33.4	0.06	0.135	714 / 379	810 / 432	914 / 490	2.02
01/20/20	05/13/20	0.0m	DISCHARGE	399 / 204	28.7	31.6	0.14	0.170	707 / 375	808 / 431	909 / 487	3.05
12/01/18	12/18/18	0.0m		295 / 146	12.1	27.9	0.034	0.117	659 / 348	794 / 423	902 / 483	7.83







Percent Recovered



Feb 8/24

## Historical Comments

20% 30% 50% 60%

01/18/23	Sample results indicate the fluid is fit for continued service. Acid Number has increased which usually is from fluid oxidation. Please ensure blanket gas is operational and re-sample in 6 months Acid Number (AN) is abnormally high.
12/06/21	sample results indicate that the fluid is in suitable condition for continued service. Please re-sample in 12 months
01/20/20	Sample results would appear to indicate that the fluid is suitable for continued service. As part of continued good maintenance practices, vent off low boiling vapors regularly (see %<335 reduction since last sample; new fluid is 1%).Please resample in 6 months and please ensure that time on fluid is recorded at next sample.
12/01/18	The fluid is in a reasonable condition and suitable for further use but there are indications of either thermal degradation, blanket gas ingress or, considering previous analysis results, indications of an internal process fluid leak. Viscosity, Flash Point and GCD 10% temperature are low. % boil-off below 335 degrees C is high. If an internal process fluid leak is suspect this has to be corrected. In any case it is recommended to vent off the low boiler vapors (light ends) to atmosphere. Please resample in 6 months. COC Flash Point is severely low. (GCD) % < 335°C is marginally high. (GCD) 10% Distillation Point is marginally low.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.