


WANSON BH/INC 1200


Customer: PTRHTF40127	System Information	Sample Information
Dalco Foods B.V	System Volume: 4200 gal	Lab No: 02624515
Everdenberg 50	Bulk Operating Temp: 518F / 270C	Analyst: Bill Quesnel CLS,OMA II,MLA-
Oosterhout, 4902TT NL	Heating Source:	III,LLA-I
Attn: Wilbert Snijers	Blanket:	Sample Date: 03/19/24
Tel:	Fluid: PETRO CANADA PURITY FG HEAT TRANSFER FLUID	Received Date: 03/25/24
E-Mail: w.snijers@klt.nl	Make: WANSON	Completed: 04/08/24
		Bill Quesnel CLS,OMA II,MLA-III,LLA-I

Recommendation: We recommend that you vent the expansion tank to remove low boilers which assists in restoring the flash point of the fluid. The fluid is suitable for further service. Resample at the next service interval to monitor.

Comments: COC Flash Point is marginally low.

Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/ g	%wt	°F/°C	°F/°C	°F/°C	%
03/19/24	03/25/24	1.3y		392 / 200	25	30.5	0.63	0.118	715 / 379	815 / 435	907 / 486	3.39
10/16/23	10/23/23	10.0y		406 / 208	31.6	29.2	0.62	0.057	695 / 368	809 / 431	906 / 486	5.35
05/31/23	06/05/23	6.0y		388 / 198	22.5	30.2	0.63	0.095	703 / 373	811 / 433	906 / 485	4.49
12/05/22	12/12/22	1.0y		435 / 224	15.7	35.5	0.73	0.085	715 / 380	814 / 434	910 / 488	3.75
07/20/22	07/26/22	4.3y		342 / 172	31.5	23.4	0.32	0.233	619 / 326	793 / 423	897 / 481	10.48





Historical Comments			
10/16/23	The flash point has increased. The fluid is suitable for further service. Resample at the next service interval to monitor.		
05/31/23	We recommend that you vent the expansion tank to remove low boilers which assists in restoring the flash point of the fluid. The fluid is suitable for further service. Resample at the next service interval to monitor. COC Flash Point is marginally low.		
12/05/22	If expansion tank venting was carried out, this has successfully restored the flash point of the fluid. Vent expansion tank every three months to remove light ends from the fluid. Fluid is suitable for continued use. Resample at next normal interval to monitor.		
07/20/22	Flash Point (COC) is very low and off specification. Recommend venting the system in order to reduce number of low boilers and recover flash point. Recommend resampling in six months to monitor. COC Flash Point is severely low. (GCD) 10% Distillation Point is abnormally low. (GCD) % < 335°C is marginally high.		

Percent Recovered

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.