



[Leland / 14-23-58-26W45] H-3700/H-3750

Customer: PTRHTF20273

CANADIAN NATURAL RESOURCES

(CNRL)

Smoky/Leland/Bistone EDSON, AB T7E 1L5 CA Attn: Rodney Marcichiw

Tel:

E-Mail: rodney.marcichiw@cnrl.com

System Information

System Volume: 10000 ltr Bulk Operating Temp: 365F / 185C

Heating Source:

Blanket:

Fluid: PETRO CANADA PETRO-THERM

Make: PETRO TECH HEATERS

Sample Information


Lab No: 02626808 Analyst: Clinton Buhler Sample Date: 03/26/24 Received Date: 04/04/24 Completed: 04/15/24


Clinton Buhler


Clinton.Buhler@HFSinclair.com


Recommendation: Sample results indicate that the fluid is in suitable condition for continued service. Flash point is marginally low, but consistent with last year's sample. Consider periodic venting of the expansion tank to help improve flash point. Please resample in 12 months.

Comments:












Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]



Historical Comments	
04/24/23	Sample results indicate the fluid is in suitable condition for continued service. The fluid's flash point has improved since the last sample in 2020. Please re-sample in 12 months.
10/20/20	Sample results indicate that the fluid is suitable for continues service. Please note that the fluid's flash point has improved since the previous sample, yet the low boiling vapor content has increased. The flash point is still low. It is advised to continue regular venting of low boiling vapors to improve the fluids flash point. Resample in 6 months once venting regime has been initiated.
03/25/20	This is the re-run of the sample taken on March 25th when a low boiler vapor content of 15.8% was reported due to a GC fault. After GC repair the low boiler vapor content is 2.39%. The other parameters remain the same. The fluid is in a reasonable condition and suitable for further use. Venting is still important to try and increase the Flash Point of the fluid. COC Flash Point is severely low.
01/30/20	The fluid is in reasonable condition and suitable for further use. Viscosity is slightly low. Flash Point is very low. This is the result of a low boiler vapor content of 8.28% which is considered high. A Flash Point below 150 degrees C is a safety concern and the low boiler vapor content at this level may result in pump cavitation, flow problems or pump seal leakage. Venting of low boiler vapor to atmosphere is recommended. Please re-sample in 6 months. COC Flash Point is severely low. (GCD) % < 335°C is marginally high.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.