



DV PTC-UNIT #3

Customer

Multimatic Engineering Services

85 Valleywood Drive

Markham, ON L3R 5E5 CA

Attn: Greg Wallace Tel: (905)470-0025

E-Mail: gwallace@multimatic.com

System Information

System Volume: 0 gal

Bulk Operating Temp: Not Specified

Heating Source:

Blanket:

Fluid: FUCHS TITAN SAF 1579 EU 175

Make:

Sample Information

Lab No: 02634370

Analyst: Bill Quesnel CLS, OMA II, MLA-

III,LLA-I

Sample Date: 05/08/24 Received Date: 05/09/24 Completed: 05/14/24

Bill Quesnel CLS, OMA II, MLA-III, LLA-I

Recommendation: We advise that you check all areas where dirt can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition.

Comments: Iron ppm levels are severe. PQ levels are severe. The very high ferrous density (PQ) index indicates that severe wear is occurring. There is a moderate concentration of dirt present in the fluid. The water content is negligible. High amount of ingressed dirt has caused abrasive wear to the component. Viscosity of sample indicates oil is within ISO 15 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The AN level is acceptable for this fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.



Report ID: [02634370] (Generated: 05/15/2024 13:22:20) - Page 1 - Copyright 2024 Wearcheck Inc. All Rights Reserved.

