



ERGON YELLOW CREEK

Customer:

ERGON - YELLOWCREEK 35 COUNTY RD 370 LUKA, MS 38852 US Attn: JIMMY FREDERICK

Tel:

E-Mail: Jimmy.Frederick@ergon.com

System Information

System Volume: 1 ltr

Bulk Operating Temp: Not Specified

Heating Source:

Blanket:

Fluid: ERGON HYGOLD L500

Make:

Sample Information

Lab No: 06186633 Analyst: Doug Bogart Sample Date: 05/17/24 Received Date: 05/21/24 Completed: 05/29/24

Doug Bogart

dougb@wearcheckusa.com

Recommendation: We recommend that you vent the expansion tank to remove low boilers which assists in restoring the flash point of the fluid. The low initial boiling point and viscosity, along with the low boilers present in the simulated distillation chromatogram indicate contamination with a volatile substance. Please review fluid safety requirements (i.e. flash point) regarding fluid operating temperatures. All tests and evaluation performed at WearCheck Canada.

Comments: (GCD) Initial Boiling Point is abnormal. Visc @ 40°C is abnormally low.









Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]

GCD Spectrum





Historical Comments

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. Please note that this is a corrected copy for oil baseline data update and diagnostic comment updates. All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The oil 08/18/23 viscosity is lower than normal. This plus the additive levels indicates the possible addition of a different brand or type of oil. Confirm oil type. The AN level is acceptable for this fluid.