## LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### [(370850)] LIEBHERR L526 048566-1558 - Diesel Engine

Sample No: LH0250787
Oil Type: SAE 5W30

<b>5</b>						
SAMPLEINFORMATION						
Sample Number	LI	H0250787				
Sample Date	30	8 Feb 2023				
Machine Hours	20	005				
Oil Hours	0					
Oil Changed	C	hanged				
Sample Status	S	EVERE				

OIL CO	ONDITION			
Visc @ 100°C	cSt	<b>7.3</b>	 	
Oxidation (PA)	%	83	 	

CONTAMINATION						
Water	%	NEG				
Soot %	%	<b>0</b>				
Nitration (PA)	%	100				
Sulfation (PA)	%	60				
Glycol	%	NEG				
Fuel	%	<b>2</b> 3				
Silicon	ppm	<b>6</b>				
Sodium	ppm	<b>4</b>				
Potassium	ppm	<b>8</b>				

₩E/	R METAI	S		
Iron	ppm	<b>30</b>	 	
Copper	ppm	<b>17</b>	 	
Lead	ppm	<b>6</b>	 	
Tin	ppm	<b>○</b> <1	 	
Aluminum	ppm	<b>6</b>	 	
Chromium	ppm	<b>1</b>	 	
Molybdenum	ppm	8	 	
Nickel	ppm	<1	 	
Titanium	ppm	<b></b> <1	 	
Silver	ppm	<b>0</b>	 	
Manganese	ppm	<b>()</b> <1	 	
Vanadium	ppm	0	 	

ADDITIVES						
Calcium	ppm	1518				
Magnesium	ppm	90				
Zinc	ppm	<b>792</b>				
Phosphorus	ppm	<b>758</b>				
Barium	ppm	<b>0</b>				
Boron	ppm	<b>29</b>				



CEDRE C. MEILLEUR
1 RANG 7
KIAMIKA, QC
CA J0W 1G0
Contact: Service Manager

T:

F:

#### Diagnosis

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is a

high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

Depot:CEDKIAUnique No:5528000Signed:Wes DavisReport Date:14 Feb 2023

# LIEBHERR







#### **GRAPHS**

