



133072 - Hydraulic System

Sample No: LH0265752

Oil Type: NOT GIVEN

=

Sample Number		LH0265752	LH0185894		
Sample Date		19 Jun 2023	10 Dec 2020		
Machine Hours		22441	19061		
Oil Hours		0	0		
Oil Changed		Not Changd	Not Changd		
Sample Status		SEVERE	SEVERE		
OIL CONDITION					
Visc @ 40°C	cSt	36.1	25.4		
**					

Particles >4µm		— 41523	173659		
Particles >6µm		0 8830	0 141976		
Particles >14µm		<mark>)</mark> 255	0 49469		
ISO 4406:1999 (c)		23/20/15	25/24/23		
Silicon	ppm	02	2		
Sodium	ppm	<mark>()</mark> <1	02		
Potassium	ppm	01	○ <1		

WEAR METALS

PQ			0	
Iron	ppm	5	27	
Copper	ppm	06	07	
Lead	ppm	○ <1	2	
Tin	ppm	0	○ <1	
Aluminum	ppm	○ <1	○ <1	
Chromium	ppm	0	○ <1	
Molybdenum	ppm	1	0	
Nickel	ppm	○ <1	<1	
Titanium	ppm	0	0	
Silver	ppm	0	<1	
Manganese	ppm	0	5	
Vanadium	ppm	0	0	

0

Calcium	ppm	82	17			
Magnesium	ppm	4	<1			
Zinc	ppm	602	207			
Phosphorus	ppm	626	553			
Barium	ppm	0	<1			
Boron	ppm	2	2			

LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8 Contact: Steve Lehto steve.lehto@liebherr.com T: (905)319-9222 F: (905)319-6617

Diagnosis

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the oil. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

Depot:	LIEMIS
Unique No:	5594374
Signed:	Kevin Marson
Report Date:	21 Jun 2023

Contact/Location: Steve Lehto - LIEMIS

CONSTRUCTION EQUIPMENT



GRAPHS

 \odot

