
# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### **C22.03.90121 - Diesel Engine**

Sample No: LH0270593
Oil Type: NOT GIVEN



#### LIEBHERR CANADA LTD. - REMAN

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Jeff Carter jeff.carter@liebherr.com T: (905)319-9222

F: (905)319-9222 F: (905)319-6622

#### Diagnosis

We advise that you check the fuel injection system. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is a high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

Depot:REMANUnique No:5607373Signed:Wes DavisReport Date:18 Jul 2023

Contact/Location: Jeff Carter - REMAN

ppm

**20** 

Boron

# LIEBHERR

CONSTRUCTION EQUIPMENT





### **GRAPHS**

