
LIEBHERR

CONSTRUCTION EQUIPMENT

2020.03.2432 - Diesel Engine

Sample No: LH0270457
Oil Type: NOT GIVEN





1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Jeff Carter jeff.carter@liebherr.com

T: (905)319-9222 F: (905)319-6622

Diagnosis

We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample. Aluminum and chromium ppm levels are abnormal. Ring wear is indicated. Piston wear is indicated. We have assumed that this component is not breaking in (age of component not reported). The water content is negligible. There is no indication of any contamination in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:REMANUnique No:5619506Signed:Kevin MarsonReport Date:08 Aug 2023

Contact/Location: Jeff Carter - REMAN

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

