
LIEBHERR

CONSTRUCTION EQUIPMENT

C22.02.90017 - Diesel Engine

Sample No: LH0270595
Oil Type: NOT GIVEN



LIEBHERR CANADA LTD. - REMAN

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Jeff Carter jeff.carter@liebherr.com T: (905)319-9222

F: (905)319-9222

Diagnosis

We advise that you check the fuel injection system. We advise that you check for the source of water entry. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is a high amount of fuel present in the oil. There is a high concentration of water present in the oil. Test for glycol is negative. Tests confirm the presence of fuel in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

Depot:REMANUnique No:5629733Signed:Kevin MarsonReport Date:21 Aug 2023

Contact/Location: Jeff Carter - REMAN

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

