LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LTR1100 074910 - Hydraulic System

4

4

2

0

<1</p>

<1</p>

<1</p>

0

0

<1

0

Report Id: LIESPR [WCAMIS] 02590673 (Generated: 10/23/2023 10:17:09) Rev: 1

ppm

Sample No: LH0250393
Oil Type: NOT GIVEN

Iron

Copper

Aluminum

Chromium

Nickel

Silver

Titanium

Manganese

Vanadium

Molybdenum

Lead

Tin

Sample Number		LH0250393	LH0104866	
Sample Date		19 Oct 2023	02 Sep 2016	
Machine Hours		8359	23257	
Oil Hours		0	0	
Oil Changed		N/A	Not Changd	
Sample Status		ABNORMAL	NORMAL	
CONT	'AMINA	TION		
CONT		TION		
	MINITA			
Particles >4µm		27979	680	
Particles >4µm Particles >6µm		○ 27979○ 4511	680151	
Particles >4µm Particles >6µm				
Particles >4µm		4511	O 151	
Particles >4µm Particles >6µm Particles >14µm	ppm	↓ 4511↓ 378	15110	
Particles >4µm Particles >6µm Particles >14µm SO 4406:1999 (c)		451137822/19/16	○ 151○ 1017/14/10	

LIEBHERR CANADA LTD.

10374 267 ST. ACHESON, AB CA T7X 6A2

Contact: Rodney Budzak rodney.budzak@liebherr.com

T: (780)962-6799 F: (780)962-6799

Diagnosis

We advise that you check all areas where dirt can enter the system. We recommend that you drain the oil from the component if this has not already been done. We recommend you service the filters on this component. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. There is a moderate concentration of dirt present in the oil. The oil is no longer serviceable due to the presence of contaminants.

ADDITIVES								
Calcium	ppm	120	127					
Magnesium	ppm	<1	<1					
Zinc	ppm	55	52					
Phosphorus	ppm	501	539					
Barium	ppm	<1	<1					
Boron	ppm	17	21					

Depot: LIESPR
Unique No: 5659739
Signed: Kevin Marson
Report Date: 23 Oct 2023

CONSTRUCTION EQUIPMENT





GRAPHS

