

### LIEBHERR PR736 26648 - Hydraulic System

Sample No: LH0225143

Oil Type: LIEBHERR HYDRAULIC HVI

### SAMPLE INFORMATION

Sample Number	LH0225143	 	
Sample Date	11 Jan 2024	 	
Machine Hours	361	 	
Oil Hours	0	 	
Oil Changed	Changed	 	
Sample Status	NORMAL	 	

**OIL CONDITION** 

Visc @ 40°C

## cSt **0 47.4**

1	

Water	%	NEG			
Particles >4µm		<b>9250</b>			
Particles >6µm		0 1591			
Particles >14µm		0 48			
ISO 4406:1999 (c)		20/18/13			
Silicon	ppm	01			
Sodium	ppm	0			
Potassium	ppm	<b>○</b> <1			

#### **WEAR METALS**

Iron	ppm	<b>○</b> <1	 	
Copper	ppm	<b>○</b> <1	 	
Lead	ppm	0	 	
Tin	ppm	0 🔘	 	
Aluminum	ppm	<b>○</b> <1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<b>○</b> <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

0

	DITIVES			
Calcium	ppm	190	 	
Magnesium	ppm	<b>○</b> <1	 	
Zinc	ppm	0 840	 	
Phosphorus	ppm	○ 665	 	
Barium	ppm	0 🔘	 	
Boron	mag	0	 	





#### LIEBHERR CANADA LTD.

10374 267 ST. ACHESON, AB CA T7X 6A2 Contact: Dustin Fluet dustin.fluet@liebherr.com T: (780)962-6088 F: (780)962-6799

#### Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:LIESPRUnique No:5711074Signed:Kevin MarsonReport Date:22 Jan 2024

Report Id: LIESPR [WCAMIS] 02609988 (Generated: 01/22/2024 12:10:05) Rev: 1

Contact/Location: Dustin Fluet - LIESPR

# **LEBHERR** CONSTRUCTION EQUIPMENT



GRAPHS

Ö

