CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 153769-1253 - Front Differential

Sample No: LH0278095

Oil Type: {unknown}

Sample Information

Sample Number	LH0278095	LH0278091	
Sample Date	02 Apr 2024	10 Mar 2024	
Machine Hours	2000	2000	
Oil Hours	0	0	
Oil Changed	Changed	N/A	
Sample Status	SEVERE	NORMAL	

Oil Condition

Visc @ 40°C
cSt
94.0
76.2
--

Contamination							
Water	%	NEG	NEG				
Silicon	ppm	0 37	0 10				
Sodium	ppm	0 2	2				
Potassium	maa	01	\bigcirc <1				

👾 Wear	Metals			
PQ		239		
Iron	ppm	487	02	
Copper	ppm	2	0 <1	
Lead	ppm	0 <1	0	
Tin	ppm	0	0	
Aluminum	ppm	3	01	
Chromium	ppm	○ <1	0	
Molybdenum	ppm	2	36	
Nickel	ppm	0	○ <1	
Titanium	ppm	4	0	
Silver	ppm	0	0	
Manganese	ppm	2	0	
Vanadium	ppm	0	0	

Additives Calcium 4113 1595 ppm Magnesium 15 463 ppm 1018 977 Zinc ppm Phosphorus 854 870 ppm Barium 0 ppm 0 Boron ppm 3 6





9262-1408 Quebec Inc. 13125 Rue Industrielle Sorel-Tracy, QC CA J3R 0E8 Contact: Service Manager

T: F:

Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. The fluid was not specified, however, a fluid match indicates that this fluid is SAE 30 Transmission/Drive Train Oil. Please confirm the oil type and grade, and specify the brand of the oil on your next sample. Iron ppm levels are severe. A sharp increase in the iron level is noted. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. There is a moderate concentration of dirt present in the oil. High amount of ingressed dirt has caused abrasive wear to the component. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot: Unique No: Signed: Report Date: 926SOR 5760209 Kevin Marson 08 Apr 2024 Submitted By: ?





Graphs

O

