

CATERPILLAR ET0417 - Hydraulic System

Sample No: LH0284099

Oil Type: PETRO CANADA 30W

Sample Information

Sample Number	mple Number		LH0260504	LH0240804	LH0192045			
Sample Date	mple Date		06 Nov 2023	26 Oct 2022	19 Mar 2022			
Machine Hours		12065	11574	10181	9424			
Oil Hours		0	0	0	0			
Oil Changed		Not Changd	N/A	Not Changd	Not Changd			
Sample Status		ABNORMAL	ABNORMAL	ABNORMAL	ABNORMAL			
Oil Co	ndition							
Visc @ 40°C	cSt	53.7	0 39.7	0 38.5	38.5			
	001	00.1	00.1	00.0	00.0			

					_
Contamination					
Water	%	NEG	NEG	NEG	NEG
Particles >4µm		3186	0 8179	2105	◯ 3301
Particles >6µm		133	125	517	0 488
Particles >14µm		0 16	07	57	◯ 43
ISO 4406:1999 (c)		19/14/11	20/14/10	18/16/13	19/16/13
Silicon	ppm	<mark>○</mark> <1	0 2	2	01
Sodium	ppm	01	0 1	2	○ <1
Potassium	ppm	01	○ <1	◯ <1	01

₩ Wee	Wear Metals					
PQ		0	0	0	0	
Iron	ppm	<u> </u>	0 37	0 26	21	
Copper	ppm	01	2	3	3	
Lead	ppm	0 🔘	○ <1	◯ <1	◯ <1	
Tin	ppm	0 🔘	0	0	0	
Aluminum	ppm	01	0 2	◯ <1	◯ <1	
Chromium	ppm	<u> </u>	0 25	0 29	0 20	
Molybdenum	ppm	0 🔘	0	◯ <1	◯ <1	
Nickel	ppm	0 🔘	○ <1	◯ <1	0	
Titanium	ppm	0	0	<1	0	
Silver	ppm	0	<1	0	<1	
Manganese	ppm	0	○ <1	◯ <1	◯ <1	
Vanadium	ppm	0	0	0	0	

Addit	ives				
Calcium	ppm	O 1310	0 148	0 173	0 169
Magnesium	ppm	<u> </u>	0 4	06	6
Zinc	ppm	587	0 212	0 385	0 397
Phosphorus	ppm	0 774	624	○ 710	685
Barium	ppm	○ <1	○ <1	0	○ <1
Boron	ppm	02	01	01	01





Radius Recycling Canada Ltd. 12195 Musqueam Dr.

Surrey, BC CA V3V 3T2 Contact: Chris Trinkunas ctrinkunas@rdus.com T: F: (604)580-1922

Diagnosis

We recommend that you drain the oil from the component if this has not already been done. Confirm the source of the lubricant being utilized for top-up/fill. We recommend an early resample to monitor this condition.Chromium and iron ppm levels are abnormal. Ring wear is indicated. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. Viscosity of sample indicates oil is within SAE 20 range, advise investigate. This plus the additive levels indicates that this is not the same brand, or type of oil as reported. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:AMISURUnique No:5760510Signed:Kevin MarsonReport Date:09 Apr 2024


Report Id: AMISUR [WCAMIS] 02627378 (Generated: 04/09/2024 11:35:26) Rev: 1

Contact/Location: Chris Trinkunas - AMISUR

LIEBHERR CONSTRUCTION EQUIPMENT



Graphs



Report Id: AMISUR [WCAMIS] 02627378 (Generated: 04/09/2024 11:35:29) Rev: 1