EBHERR

CONSTRUCTION EQUIPMENT

2018.03.3854 - Diesel Engine

Sample No: LH0276248 Oil Type: **SAE 5W30**





LIEBHERR CANADA LTD. - REMAN

1015 SUTTON DRIVE BURLINGTON, ON

CA L7L 5Z8

Contact: Morteza Mahmoudi morteza.mahmoudi@liebherr.com

T: (905)319-9222 F: (905)319-6622

Diagnosis

We advise that you check the fuel injection system. We advise that you check for the source of the coolant leak. We recommend that you drain the oil from the component if this has not already been done. We advise that you flush the component thoroughly before re-filling with oil. We recommend an early resample to monitor this condition. Metal levels are typical for a new component breaking in. Test for glycol is positive. There is a high amount of fuel present in the oil. There is a moderate concentration of glycol present in the oil. There is a moderate concentration of water present in the oil. Tests confirm the presence of fuel in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

Depot: REMAN **Unique No:** 5773377 Signed: Kevin Marson Report Date: 01 May 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

