LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L586 070058-1761 - Rear Differential

Sample No: LH

Iron

Copper

Aluminum

Chromium

Nickel

Silver

Titanium

Manganese

Molybdenum

Lead

Tin

Oil Type: NOT GIVEN

Sample Number		LH	LH0260171	
Sample Date		03 May 2024	19 May 2023	
Machine Hours		3352	1026	
Oil Hours		0	0	
Oil Changed		Not Changd	Changed	
Sample Status		ABNORMAL	NORMAL	
/isc @ 40°C	cSt taminati	○ 92.8	193	
Water	%	NEG	NEG	
Silicon	ppm	10	O 22	
Sodium	ppm	3	O 4	
Potassium	ppm	O <1	0 <1	
A	ar Metal:			

149

05

248

172

3

0 11

<1</p>

2

<1</p>

0

0

0

18

ppm

	1
	588
	0
3	
- 10	

Gravier Collet Gravel SW31-6-8W Notre Dame de Lourdes, MB CA R0G 1M0 Contact: Service Manager

T: F:

Diagnosis

We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. Tin ppm levels are abnormal. Bearing and/or bushing wear is indicated. There is no indication of any contamination in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Vanadium	ppm	0	<1						
Additives									
Calcium	ppm	13	9						
Magnesium	ppm	2	<1						
Zinc	ppm	52	34						
Phosphorus	ppm	2182	2490						
Barium	ppm	<1	0						
Boron	ppm	252	<1						

36

Depot: GRANOT
Unique No: 5775070
Signed: Kevin Marson
Report Date: 07 May 2024

Submitted By: Vincent Blanchette

CONSTRUCTION EQUIPMENT





Graphs

