# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### LIEBHERR LH50M 077508 - Swing Drive

Sample No: LH0289764
Oil Type: {unknown}

Sample Information						
Sample Number	LH0289764					
Sample Date	01 May 2024					
Machine Hours	16364					
Oil Hours	0					
Oil Changed	N/A					
Sample Status	ABNORMAL					
A						

Campic .	Otatas		ADITOTUMAL		
0	Oil Co	ndition			
Visc @ 4	40°C	cSt	<b>100</b>	 	
-4					

Contamination							
Water	%	NEG					
Silicon	ppm	<b>3</b>					
Sodium	ppm	<b>3</b>					
Potassium	ppm	<b>○</b> <1					

(O) Was	_			
Wed	ır Metal:	5		
Iron	ppm	<b>85</b>	 	
Copper	ppm	<b>120</b>	 	
Lead	ppm	<b>2</b>	 	
Tin	ppm	<b>5</b>	 	
Aluminum	ppm	<b></b> <1	 	
Chromium	ppm	<b>()</b> <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	<b>0</b>	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	

Additives						
Calcium	ppm	15				
Magnesium	ppm	436				
Zinc	ppm	20				
Phosphorus	ppm	1313				
Barium	ppm	0				
Boron	ppm	282				



J.M. BASTILLE ACIER INC 396 RUE TEMISCOUATA,, CP 744 RIVIERE DU LOUP, QC CA G5R 3Z3 Contact: MANAGER SERVICE

T: (418)862-3346 F:

#### Diagnosis

We advise that you check for the source of water entry. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. Free water present. The oil is no longer serviceable due to the presence of contaminants.

Depot:JMBRIVUnique No:5776162Signed:Kevin MarsonReport Date:13 May 2024

# LIEBHERR







### **Graphs**

