

[CNRL] 2210 - Hoist

Sample No: LH0265155 **Oil Type:** {unknown}

Sample Information

Sample Number	LH0265155	 	
Sample Date	26 Jun 2024	 	
Machine Hours	25320	 	
Oil Hours	0	 	
Oil Changed	Not Changd	 	
Sample Status	ΔΤΤΕΝΤΙΟΝ	 	

38.6

Oil Condition

Visc @ 40°C

,	CSI	

Conta	mination			
Water	%	NEG	 	
Particles >4µm		2652	 	
Particles >6µm		786	 	
Particles >14µm		0 86	 	
ISO 4406:1999 (c)		19/17/14	 	
Silicon	ppm	8 🔘	 	
Sodium	ppm	○ <1	 	
Potassium	ppm	<mark>○</mark> <1	 	

Wear Metals

Iron	ppm	02			
Copper	ppm	○ <1			
Lead	ppm	0			
Tin	ppm	0			
Aluminum	ppm	01			
Chromium	ppm	0			
Molybdenum	ppm	<1			
Nickel	ppm	<mark>○</mark> <1			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	0			
Vanadium	ppm	0			

Additives					
Calcium	ppm	3290			
Magnesium	ppm	13			
Zinc	ppm	1031			
Phosphorus	ppm	867			
Barium	ppm	0			
Boron	ppm	1			





Liebherr-Canada Ltd.

Fort McKay Industrial Park, Lot No. 12 and 13 Fort McMurray, AB CA T9H 5N3 Contact: Corey Ekroth corey.ekroth@liebherr.com T: (780)791-2967 F:

Diagnosis

We recommend you service the filters on this component. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. The condition of the oil is acceptable for the time in service.

LIEFTM Depot: Unique No: 5803081 Signed: Kevin Marson **Report Date:** 12 Jul 2024

LEBHERR CONSTRUCTION EQUIPMENT



Graphs

Ö

