# E **CONSTRUCTION EQUIPMENT**

## LIEBHERR L546 054052-1560 - Front Left Wheel Hub

Sample No: LH0169006

**Oil Type:** GEAR OIL SAE 75W90

### Sample Information

Sample Number	LH0169006	LH0169032	LH0169019	LH0168993
Sample Date	11 Jun 2024	10 Jan 2023	15 Sep 2022	14 Jun 2021
Machine Hours	7137	4988	4420	2095
Oil Hours	0	0	0	0
Oil Changed	Changed	Changed	Not Changd	Changed
Sample Status	ABNORMAL	ABNORMAL	ABNORMAL	NORMAL
Oil Condition				
Visc @ 40°C cSt	<b>0</b> 109	122	122	0 106
<b>1</b>				

Con	ntaminati	ion				
Water	%	NEG	NEG	NEG	NEG	
Silicon	ppm	<b>○</b> <1	○ 5	01	8	
Sodium	ppm	0 2	2	2	2	
Potassium	ppm	0 4	○ 5	0 4	◯ <1	

Â					
₩ Wee	ar Metals	5			
PQ		0	0	0	
Iron	ppm	<u> </u>	0 769	0 494	54
Copper	ppm	<b>()</b> <1	◯ <1	◯ <1	○ <1
Lead	ppm	0 (	0	0	○ <1
Tin	ppm	0	0	0	0
Aluminum	ppm	<mark></mark> <1	01	◯ <1	○ <1
Chromium	ppm	06	9	0 6	○ <1
Molybdenum	ppm	<b>○</b> <1	0	0	○ <1
Nickel	ppm	<b></b> <1	0 1	◯ <1	○ <1
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	<1
Manganese	ppm	03	0 6	0 4	01
Vanadium	ppm	0	<1	0	0

Additives						
Calcium	ppm	0 12	08	6	18	
Magnesium	ppm	0 6	○ <1	○ <1	01	
Zinc	ppm	0 12	0 14	0 12	12	
Phosphorus	ppm	582	0 835	706	0 1127	
Barium	ppm	0 🔘	0	0	◯ <1	
Boron	ppm	03	06	05	07	



#### MOOREFIELD EXCAVATING LTD.

6297 WELLINGTON RD. 109S, RR #3 HARRISTON, ON CA N0G 1Z0 Contact: John Landman info@moorefieldex.ca T: (519)343-3571 F: (519)510-3277

### Diagnosis

The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. Iron ppm levels are abnormal. The low ferrous density (PQ) index indicates the wear metal levels are due to corrosion. There is no indication of any contamination in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot: Unique No: Signed: **Report Date:** 

MOOPAL 5812306 Kevin Marson 10 Jul 2024 Submitted By: ?





Graphs

Ó

