## LIEBHERR

CONSTRUCTION EQUIPMENT

### LIEBHERR R944BEW 012047-653 - Diesel Engine

Sample No: LHMC91087

Titanium

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

Silver

ppm

**ADDITIVES** 

Oil Type: DRYDENE DUAL RANGE HYD 15W30

SAME	PLE INFOR	<b>EMATION</b>		
Sample Number		LHMC91087	LHMC100336	 
Sample Date		07 Nov 2023	13 Feb 2023	 
Machine Hours		0	0	 
Oil Hours		500	0	 
Oil Changed		Changed	N/A	 
Sample Status		SEVERE	MARGINAL	 
OIL CO	ONDITION	1		
Visc @ 100°C	cSt	<b>6.9</b>	O 12.3	 
Base Number (BN)	mg KOH/g	○ 8.9	O 6.6	 
Oxidation (PA)	%	47	76	 
-4				
CONT	AMINAT	ION		
Soot %	%	0.2	0.5	 
Nitration (PA)	%	78	93	 
Sulfation (PA)	%	47	60	 
Glycol	%	NEG	NEG	 
Fuel	%	24.5	O 3.4	 
Silicon	ppm	<b>20</b>	<b>O</b> 5	 
Sodium	ppm	<b>362</b>	O 2	 
Potassium	ppm	<b>58</b>	O 2	 
<b>**</b>				
<b>◎</b> WEΔI	R METALS			
Iron	ppm	<b>28</b>	O 28	 
Copper	ppm	<b>84</b>	0 <1	 
Lead	ppm	O 15	01	 
Tin	ppm	0 2	0 <1	 
Aluminum	ppm	0 4	05	 
Chromium	ppm	01	01	 
Molybdenum	ppm	42	O 14	 
Nickel	ppm	O <1	00	 
		_	_	

2219

0 1053

0 864

0

0 121



#### RECO EQUIPMENT INC.

20620 ROUTE 19 NORTH CRANBERRY TOWNSHIP, PA US 16066

Contact: RICK STARINCHAK RAS@RECOEQUIP.COM

T: (724)779-4646 F: (724)779-4611

#### Diagnosis

We advise that you check for the source of the coolant leak. Check for low coolant level. We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. Sodium and/or potassium levels are high. There is a high amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil.

Depot: LEC0070
Unique No: 10739819
Signed: Jonathan Hester
Report Date: 16 Nov 2023

Contact/Location: RICK STARINCHAK - LEC0070

**0** 

<1

1099

266

863

701

0

# LIEBHERR

CONSTRUCTION EQUIPMENT





#### **GRAPHS**

