LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH40M 093999-1215 - Swing Drive

Sample No: LH0243896

Oil Type: LIEBHERR GEAR BASIC 90 LS

EH0243896 28 Feb 2024 13886 0 Changed SEVERE ION 248 ATION 1.16 10 2			
28 Feb 2024 13886 0 Changed SEVERE ION 248 ATION 1.16 10 2			
13886 0 Changed SEVERE ION 248 ATION 1.16 10 2			
O Changed SEVERE ION 248 ATION 1.16 10 2			
Changed SEVERE ION 248 ATION 1.16 10 2			
SEVERE 10N 248 ATION 1.16 10 2			
248 ATION 1.16 10 2			
○ 248ATION○ 1.16○ 10○ 2			
○ 248ATION○ 1.16○ 10○ 2			
1.16 10 2			
● 1.16 ○ 10 ○ 2			
● 1.16 ○ 10 ○ 2			
● 1.16 ○ 10 ○ 2			
① 10 ② 2			
2			
-			
A 0			
2			
ALS			
2902			
720			
0 <1			
23			
0 <1			
28			
0			
4			
<1			
<1			
21			
	23 <1 28 0 4 <1 <1 <1 <1	○ 23 ○ <1 ○ 28 ○ 0 ○ 4 <1 <1 ○ 21	○ 23 ○ <1



LIEBHERR EQUIPMENT SOURCE

4100 CHESTNUT AVENUE NEWPORT NEWS, VA US 23607

Contact: LUKE APPLEBY Lucas.Appleby@liebherr.com

T:

F: (757)298-8700

Diagnosis

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Bearing and/or gear wear is indicated. There is a high concentration of water present in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot: LIEBHERRUS
Unique No: 10915871
Signed: Jonathan Hester
Report Date: 19 Mar 2024

26

130

2306

4

0

2

ADDITIVES

mqq

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

CONSTRUCTION EQUIPMENT





GRAPHS

