

TDTO FLUID SAE 50

LH0243244

20 Mar 2024 1271

Not Changd

NORMAL

1271

HITACHI ZW370-6 15586 (S/N 6108) - Rear Differential

Sample No: LH0243244

Oil Type:

SAMPLE INFORMATION

Sample Number
Sample Date
Machine Hours
Oil Hours
Oil Changed
Sample Status

nple	Status		
	— ——	 	_

OIL CONDITION

Visc @ 40°C

cSt 🔘 184.9

Water	%	NEG			
Silicon	ppm	0 38			
Sodium	ppm	0 2			
Potassium	ppm	02			

Ä				
WEA	R METALS			
Iron	ppm	203	 	
Copper	ppm	5 9	 	
Lead	ppm	01	 	
Tin	ppm	4	 	
Aluminum	ppm	02	 	
Chromium	ppm	02	 	
Molybdenum	ppm	○ <1	 	
Nickel	ppm	<mark>○</mark> <1	 	
Titanium	ppm	<1	 	
Silver	ppm	<1	 	
Manganese	ppm	02	 	
Vanadium	ppm	0	 	

ADDITIVES

Calcium	ppm	0 3565			
Magnesium	ppm	0 15			
Zinc	ppm	0 2191			
Phosphorus	ppm	0 1223			
Barium	ppm	01			
Boron	ppm	0 107			





RECO EQUIPMENT INC

8075 PRODUCTION DRIVE FLORENCE, KY US 41042 Contact: TRACEY EDGERTON tedgerton@recoequip.com T: F: (859)727-7974

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LEC0082Unique No:10940978Signed:Doug BogartReport Date:22 Mar 2024






Ferrous Alloys

GRAPHS

Ö



Report Id: LEC0082 [WUSCAR] 06126827 (Generated: 03/22/2024 16:19:08) Rev: 1