# **CONSTRUCTION EQUIPMENT**

## LIEBHERR LH50M 1216-118289 - Splitter Box

Sample No: LH06135808

0

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

**Additives** 

ppm

ppm

ppm

ppm

ppm

ppm

**Oil Type:** GEAR OIL SAE 80W90

## **Sample Information**

Sample Number	LH06135808	LH05695874	LH05370569	
Sample Date	31 Mar 2024	15 Nov 2022	10 Oct 2021	
Machine Hours	5050	0	1635	
Oil Hours	0	0	0	
Oil Changed	Not Changd	N/A	N/A	
Sample Status	SEVERE	ABNORMAL	NORMAL	



Cor	ntaminati	on			
Water	%	NEG	NEG	NEG	
Silicon	ppm	0 5	○ <1	◯ <1	
Sodium	ppm	0 49	0 1	0 4	
Potassium	ppm	0 18	0 0	02	

Ä					
Wea	<mark>ır Metal</mark> s	5			
Iron	ppm	66	55	22	
Copper	ppm	0 206	0 30	2	
Lead	ppm	<b>○</b> <1	0	◯ <1	
Tin	ppm	0 2	01	◯ <1	
Aluminum	ppm	03	◯ <1	0 4	
Chromium	ppm	<b>○</b> <1	◯ <1	◯ <1	
Molybdenum	ppm	0	◯ <1	◯ <1	
Nickel	ppm	0 (	0	0	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	<1	
Manganese	ppm	0 14	◯ <1	2	
Vanadium	ppm	<1	0	0	

25

00

08

 $\bigcirc 0$ 

04

678

0 50

 $\bigcirc 7$ 

0 57

 $\bigcirc 2$ 

 $\bigcirc 4$ 

0 1513

Diagnosis

F:

We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.Bearing and/or bushing wear is indicated. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

Depot:	KO
Unique No:	109
Signed:	Dor
Report Date:	04 /

### VIND 955273 n Baldridge Apr 2024 Submitted By: ? Page 1 of 2

3214

0 1131

0 1115

09

01

03











Graphs

