LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH80M 1218-157090 - Splitter Box

Sample No: LH0282885 Oil Type: SAE 30W

_				
J Sami	ple Info	rmation		
Sample Number		LH0282885	LH0282896	
Sample Date		19 Apr 2024	19 Mar 2024	
Machine Hours		997	545	
Oil Hours		0	0	
Oil Changed		Changed	Not Changd	
Sample Status		ATTENTION	ATTENTION	
A Clare		ATTENTION	71112111011	
A	E0.0			
Oil Co	ondition			
Visc @ 40°C	cSt	191	O 192	
Comb	uminati	.		
Water	%	NEG	NEG	
Silicon	ppm	5	O <1	
Sodium	ppm	1	O 4	
Potassium	ppm	4	O 1	
◎ Wea				
Wea	r Metal:	5		
Iron	ppm	18	O 11	
Copper	ppm	2	O 1	
Lead	ppm	0 <1	O 0	
Tin	ppm	O <1	O 2	
Aluminum	ppm	3	O <1	
Chromium	ppm	O <1	0	
Molybdenum	ppm	O <1	O 0	
Nickel	ppm	0 <1	O 0	
Titanium	ppm	0 <1	0	
Silver	ppm	<1	0	
Manganese	ppm	2	O 1	
Vanadium	ppm	<1	<1	
THE STATE OF THE S				
Addi	tives			
Calcium	ppm	32	O 25	
Magnesium	ppm	O 32	0 0	
Zinc	ppm	<u>0</u> 29	0 16	
Phosphorus		0 1731	0 1690	
Hospilolus	ppm	U 1731	0.000	

 \bigcirc 0



KINDER MORGAN

4301 IVERSON TRINITY, AL US 35601

Contact: RICKY JOHNSON ricky_johnson@kindermorgan.com

T:

F: (256)355-5250

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is higher than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

Depot: KINTRI
Unique No: 11090308
Signed: Sean Felton
Report Date: 25 Jun 2024

1

2

ppm

ppm

Barium

Boron







Graphs

