# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

## LIEBHERR L566 1484-59325 - Splitter Box

Sample No: LH0293981
Oil Type: {unknown}

ā								
Sample Information								
Sample Number		LH0293981						
Sample Date		27 Jun 2024						
Machine Hours		5296						
Oil Hours		0						
Oil Changed		Changed						
Sample Status		SEVERE						
A								

sample	Status		SEVERE	 	
<b>A</b>					
<b>(</b>	Oil Co	ndition			
Visc @	40°C	cSt	<b>132</b>	 	

Contamination							
Water	%	NEG					
Silicon	ppm	<b>42</b>					
Sodium	ppm	<b>()</b> <1					
Potassium	ppm	<b>3</b>					

(O) Woo				
Wed	ır Metals	3		
Iron	ppm	<b>278</b>	 	
Copper	ppm	<b>2</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>26</b>	 	
Chromium	ppm	<b>2</b>	 	
Molybdenum	ppm	3	 	
Nickel	ppm	<b>3</b>	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	

Additives						
Calcium	ppm	278				
Magnesium	ppm	59				
Zinc	ppm	248				
Phosphorus	ppm	562				
Barium	ppm	7				
Boron	ppm	20				



MR BULTS INC 2627 E 139TH ST BURNHAM, IL US 60633

Contact: SERVICE MANAGER

T: (708)868-0059 F:

#### Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. High concentration of visible metal present. Gear wear is indicated. Elemental levels of silicon (Si) and aluminum (Al) indicate aluminasilicate (coarse dirt) ingress. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:MRBBURLHUnique No:11125958Signed:Don BaldridgeReport Date:17 Jul 2024

# CONSTRUCTION EQUIPMENT





### **Graphs**

