**CONSTRUCTION EQUIPMENT** 



## [(370850)] LIEBHERR L526 048566-1558 - Diesel Engine

Sample No: LH0250787 Oil Type: **SAE 5W30** 

Ō INFOR	MATION SUR L'ÉCHAN	ITILLON	
Numéro d'échant.	LH0250787		 
Date d'échant.	08 Feb 2023		 
Heures de la Machine	2005		 
Heures de l'huile	0		 
Huile changée	Changed		 
Ctatut da l'achant	CEVEDE		

Statut de l'echant.		SEVERE					
ÉTAT D'HUILE							
Visc 100°C	cSt	<b>7.3</b>					
Oxydation (PA)	%	83					

CONT	<b>TAMIN</b>	ATION		
- COM		AIIOII		
Eau	%	NEG	 	
% de suie	%	<b>0</b>	 	
Nitration (PA)	%	100	 	
Sulfatation (PA)	%	60	 	
Glycol	%	NEG	 	
Essence	%	<b>23</b>	 	
Silicium	ppm	<b>6</b>	 	
Sodium	ppm	<b>4</b>	 	
Potassium	ppm	<b>8</b>	 	

₩é1	IAUX D'U	ISURE		
Fer	ppm	<b>30</b>	 	
Cuivre	ppm	<b>17</b>	 	
Plomb	ppm	<b>6</b>	 	
Étain	ppm	<1	 	
Aluminium	ppm	<b>6</b>	 	
Chrome	ppm	<b>1</b>	 	
Molybdène	ppm	8	 	
Nickel	ppm	<b></b> <1	 	
Titane	ppm	<1	 	
Argent	ppm	<b>0</b>	 	
Manganèse	ppm	<b></b> <1	 	
Vanadium	ppm	0	 	

ADI	DITIFS			
Calcium	ppm	1518	 	
Magnésium	ppm	90	 	
Zinc	ppm	<b>792</b>	 	
Phosphore	ppm	<b>758</b>	 	
Baryum	ppm	<b>0</b>	 	
Bore	ppm	<b>29</b>	 	



**CEDRE C. MEILLEUR** 1 RANG 7 KIAMIKA, QC CA J0W 1G0

Contact: Service Manager

T: F:

### Diagnostic

We advise that you check the fuel injection system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is a

high amount of fuel present in the oil. Tests confirm the presence of fuel in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

Depot: **CEDKIA** Unique No: 5528000 Signed: Wes Davis **Report Date:** 14 Feb 2023

# LIEBHERR







## **GRAPHS**

