



LIEBHERR LR636 017973-1275 - Hydraulic System

Sample No: LH0274572

Oil Type: SAE 10W

INFORMATION SUR L'ÉCHANTILLON					
Numéro d'échant.	LH0274572				
Date d'échant.	29 Aug 2023				
Heures de la Machine	5150				
Heures de l'huile	0				
Huile changée	Not Changd				
Statut de l'echant.	ABNORMAL				

ÉTAT D'HUILE

Visc 40°C

-

-

cSt

0 40.7

	TAMIN	ATION		
Particules >4µ		O 72185	 	
Particules >6µ		O 23670	 	
Particules >14µ		<u> </u>	 	
ISO 4406:1999 (c	:)	23/22/18	 	
Silicium	ppm	03	 	
Sodium	ppm	8 🔘	 	
Potassium	ppm	01	 	

Métaux d'Usure

Fer	ppm	0 11	 	
Cuivre	ppm	O 30	 	
Plomb	ppm	02	 	
Étain	ppm	0 0	 	
Aluminium	ppm	02	 	
Chrome	ppm	○ <1	 	
Molybdène	ppm	0 🔘	 	
Nickel	ppm	○ <1	 	
Titane	ppm	0	 	
Argent	ppm	0	 	
Manganèse	ppm	○ <1	 	
Vanadium	ppm	0	 	

ADDITIFS					
Calcium	ppm	665			
Magnésium	ppm	04			
Zinc	ppm	529			
Phosphore	ppm	0 476			
Baryum	ppm	0 🔘			
Bore	ppm	○ <1			



CON-DRAIN LTD. 30 FLORAL PARKWAY CONCORD, ON CA L4K 4R1 Contact: B BAXTER B.BAXTER@CONDRAIN.COM T:

F:

Diagnostic

We recommend you service the filters on this component. We recommend an early resample to monitor this condition.Copper ppm levels are abnormal. Bearing and/or bushing wear is indicated. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot: Unique No: Signed: Report Date: CON30CON 5633463 Kevin Marson 06 Sep 2023

CONSTRUCTION EQUIPMENT



GRAPHS

Ö

