LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30 082384-1203 - Rear Differential

Sample No: LH0269887
Oil Type: NOT GIVEN

| INFORMAT | ION SUR L'ÉCHA | NTILLON | | |
|----------------------|----------------|---------|--|--|
| Numéro d'échant. | LH0269887 | | | |
| Date d'échant. | 07 Sep 2023 | | | |
| Heures de la Machine | 11160 | | | |
| Heures de l'huile | 0 | | | |
| Huile changée | Not Changd | | | |
| Statut de l'echant. | NORMAL | | | |
| | | | | |
| ÉTATBUME | | | | |

| ÉTA | T D'HUIL | E | | |
|-----------|----------|-------------|------|--|
| Visc 40°C | cSt | 90.3 | | |
| -1 | | | | |

| CONTAMINATION | | | | | | | | |
|---------------|-----|----------|--|--|--|--|--|--|
| Silicium | ppm | 2 | | | | | | |
| Sodium | ppm | 3 | | | | | | |
| Potassium | ppm | 0 | | | | | | |
| - | | | | | | | | |

| MéT | AUX D'U | SURE | | |
|-----------|---------|----------|------|--|
| Fer | ppm | 8 | | |
| Cuivre | ppm | 7 | | |
| Plomb | ppm | 0 | | |
| Étain | ppm | 0 | | |
| Aluminium | ppm | <1 | | |
| Chrome | ppm | 0 | | |
| Molybdène | ppm | 0 | | |
| Nickel | ppm | <1 | | |
| Titane | ppm | 0 | | |
| Argent | ppm | 0 | | |
| Manganèse | ppm | <1 | | |
| Vanadium | ppm | 0 | | |

| ADDITIFS | | | | | | |
|-----------|-----|-----|--|--|--|--|
| Calcium | ppm | 323 | | | | |
| Magnésium | ppm | 25 | | | | |
| Zinc | ppm | 165 | | | | |
| Phosphore | ppm | 851 | | | | |
| Baryum | ppm | <1 | | | | |
| Bore | ppm | 29 | | | | |



BOURQUE METAL

1341 Chemin Magenta Ouest Brigham, QC CA J2K 4A2

Contact: Service Manager

T: F:

Diagnostic

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:BOU134BRIUnique No:5645572Signed:Wes DavisReport Date:21 Sep 2023

LIEBHERR







GRAPHS

