

LIEBHERR R924 054969-1487 - Hydraulic System

Sample No: LH0278948

Oil Type: LIEBHERR HYDRAULIC HVI

INFORMATION SUR L'ÉCHANTILLON

0 42.9

Numéro d'échant.	LH0278948	 	
Date d'échant.	26 Jan 2024	 	
Heures de la Machine	2495	 	
Heures de l'huile	0	 	
Huile changée	Not Changd	 	
Statut de l'echant.	ABNORMAL	 	

ÉTAT D'HUILE

Visc 40°C

cSt

11								
Eau	%	NEG						
Particules >4µ		0 4256						
Particules >6µ		0 751						
Particules >14µ		0 31						
ISO 4406:1999 (c)		19/17/12						
Silicium	ppm	05						
Sodium	ppm	0 4						
Potassium	ppm	01						
- adda								

Métaux d'Usure						
Fer	ppm	06				
Cuivre	ppm	6 3				
Plomb	ppm	<mark>)</mark> 9				
Étain	ppm	2				
Aluminium	ppm	01				
Chrome	ppm	<mark></mark> <1				
Molybdène	ppm	0				
Nickel	ppm	0				
Titane	ppm	0				
Argent	ppm	0				
Manganèse	ppm	0				
Vanadium	ppm	0				

0 **ADDITIFS** Calcium 0 1077 ppm 04 Magnésium ppm Zinc ppm 682 Phosphore 0 579 ppm Baryum 0 ppm Bore ○ <1 ppm





CLOUTHIER VENTURES LTD.

59 MATTHEWS STREET, R.R. # 5 PEMBROKE, ON CA K8A 0A6 Contact: Travis Bennett tbennett@clouthierconst.com T: (613)735-6531 F: (613)735-2769

Diagnostic

We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.Copper and lead ppm levels are abnormal. Bearing and/or bushing wear is indicated. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot: Unique No: Signed: Report Date: CLOPEM 5722868 Bill Quesnel 06 Feb 2024

Submitted By: ?

CONSTRUCTION EQUIPMENT



GRAPHS

Ö

