


PROBLEM SUMMARY

Fwd Machinery Space [450164935] Machine Id Thruster Aft Port - Steering Tube Seal (S/N Sample Tag CL-06002-S5) Component Steering Eluid

CASTROL ALPHA SP150 (35 LTR)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS Sample Status SEVERE SEVERE ABNORMAL Particles >4µm ASTM D7647 >2500 030533 328396 ▲ 13226 Particles >6µm ASTM D7647 >640 9290 135250 A 2483 Particles >14µm ASTM D7647 >80 737 **5**387 56 Particles >21um ASTM D7647 >20 199 1285 13 Particles >38µm ASTM D7647 >4 ▲ 30 0 **Oil Cleanliness** ISO 4406 (c) >18/16/13 **22/20/17** 26/24/20 ▲ 21/18/13


Customer Id: TERHAM Sample No.: PC Lab Number: 02573832 Test Package: MAR 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com



RECOMMENDED AC	CTIC	DNS
----------------	------	-----

Action	Status	Date	Done By	Description
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.
Resample			?	Resample in 30-45 days to monitor this situation.
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.

HISTORICAL DIAGNOSIS



30 Sep 2020 Diag: Kevin Marson

Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you use off-line filtration with water adsorbent filters to attempt to remove the water from this fluid. We recommend that you drain the fluid from the component if this has not already been done. We recommend that you change the oil. Resample in 30-45 days to monitor this situation. Chromium, iron and nickel ppm levels are abnormal. Particles >14µm are severely high. Particles >21µm are severely high. Particles >6µm are severely high. Particles >4µm are severely high. Particles >4µm are severely high.. Particles >4µm are severely high... Particles >38µm are abnormally high. There is a moderate concentration of water present in the fluid. Free water present. The white residue present in the sample is fluid additive precipitate. The AN level is acceptable for this fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.





06 May 2020 Diag: Kevin Marson

We recommend you service the filters on this component. We recommend an early resample to monitor this condition.All component wear rates are normal. Particles >4µm are abnormally high. Particles >6µm are abnormally high. The AN level is acceptable for this fluid. The condition of the fluid is suitable for further service.





15 Apr 2020 Diag: Kevin Marson Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. We advise that you follow the water drain-off procedure for this component, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather We recommend that you change the oil. We recommend you service the filters on this component. Confirm the source of the lubricant being utilized for top-up/fill. Resample in 30-45 days to monitor this situation. No other corrective action is recommended at this time. Chromium and iron and nickel ppm levels are severe. PQ levels are abnormal. Wear particle analysis indicates that the ferrous rubbing and ferrous corrosive particles are abnormal. Wear particle analysis indicates that the ferrous rolling particles are marginal. The high ferrous density (PQ) index indicates that abnormal wear is occurring. ppm Water and water contamination levels are severe. Particles >38µm are severely high. Particles >6µm are severely high. Particles >71µm are severely high. Particles >21µm are severely high levels indicate the addition of a different brand, or type of oil. The white residue present in the sample is fluid additive precipitate. The fluid is no longer serviceable as a result of the abnormal and/or severe wear





OIL ANALYSIS REPORT

Sample Number

Sample Date

Machine Age

Oil Changed

Sample Status

WEAR METALS

Oil Age

PQ

Iron

Nickel

Silver

Particles >71µm

Oil Cleanliness

Titanium

Chromium

Fwd Machinery Space [450164935] Thruster Aft Port - Steering Tube Seal (S/N Sample Tag CL-06002-S5) Component Steering

Fluid CASTROL ALPHA SP150 (35 LTR)

DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

Wear


All component wear rates are normal.

Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the fluid.

Fluid Condition

The AN level is acceptable for this fluid. The fluid is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



Aluminum	ppm	ASTM D5185(m)	>5	<1	<1	<1
Lead	ppm	ASTM D5185(m)	>10	0	0	0
Copper	ppm	ASTM D5185(m)	>50	<1	<1	<1
Tin	ppm	ASTM D5185(m)	>5	0	0	0
Antimony	ppm	ASTM D5185(m)		0	<1	<1
Vanadium	ppm	ASTM D5185(m)		0	<1	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		14	3	4
Barium	ppm	ASTM D5185(m)	4	0	0	<1
Molybdenum	ppm	ASTM D5185(m)		0	1	0
Manganese	ppm	ASTM D5185(m)		0	1	<1
Magnesium	ppm	ASTM D5185(m)	4	<1	2	1
Calcium	ppm	ASTM D5185(m)	4	1	3	1
Phosphorus	ppm	ASTM D5185(m)	330	184	258	298
Zinc	ppm	ASTM D5185(m)	4	6	4	7
Sulfur	ppm	ASTM D5185(m)		9782	8138	8602
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINAN	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	3	2	2

Silicon	ppm	ASTM D5185(m)	>15	3	2	2
Sodium	ppm	ASTM D5185(m)		0	8	<1
Potassium	ppm	ASTM D5185(m)	>20	<1	<1	<1
FLUID CLEANL	INESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>2500	• 30533	928396	13226
Particles >6µm		ASTM D7647	>640	9290	135250	4 2483
Particles >14µm		ASTM D7647	>80	e 737	b 5387	56
Particles >21µm		ASTM D7647	>20	🛑 199	1285	13
Particles >38µm		ASTM D7647	>4	<u> </u>	A 30	0

ISO 4406 (c) >18/16/13 **22/20/17**

1

ASTM D7647 >3

0

21/18/13

0

26/24/20



Particle Count

Particle Trend

orma

Acid Number

144

Aav6/20

214

38/

491,520 122 880

30

2,500 Ê 2,000 a of particles (1 and 1,000) and 1,000

500

0k

16

Vumber (mg KOH/g) 0.6

-Pg 0.4

0.2


April

OIL ANALYSIS REPORT

FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		0.46	0.36	0.43
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Precipitate	scalar	Visual*	NONE	NONE	🔺 LIGHT	NONE
Silt	scalar	Visual*	NONE	NONE	NONE	NONE
Debris	scalar	Visual*	NONE	VLITE	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	NONE
Appearance	scalar	Visual*	NORML	NORML	NORML	NORML
Odor	scalar	Visual*	NORML	NORML	NORML	NORML
Emulsified Water	scalar	Visual*	>0.2	NEG	.5%	NEG
Free Water	scalar	Visual*		NEG	▲ 1%	NEG
FLUID PROPE	RTIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	150.0	142	143	142
Visc @ 100°C	cSt	ASTM D7279(m)	14.5	14.2	14.2	14.0
Viscosity Index (VI)	Scale	ASTM D2270*	95	97	96	94
SAMPLE IMAG	ES	method	limit/base	current	history1	history2
						- 7
0.1						

Color

Bottom



: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Suncor - Terra Nova Projects Received : 02 Aug 2023 Scotia Centre, 235 Water Strret Diagnosed : 03 Aug 2023 St. John`s, NL Diagnostician : Kevin Marson CA A1C 1B6 Test Package : MAR 2 (Additional Tests: KV100, PQ, PrtCount, VI) Contact: Josh Hynes joshynes@suncor.com T: (709)778-3575 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied. F: (709)724-2835