

PROBLEM SUMMARY

Sample Rating Trend

ISO

<u>Are</u>a


Fwd Machinery Space [450188488]

Thruster Fwd Aft - Seal Oil System (S/N Sample Tag CL-06005-S3)


Component

Sealing System

PETRO CANADA ENERGOL GR-XP ISO 150 (65 LTR)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS							
Sample Status			SEVERE	NORMAL	NORMAL		
Particles >4µm	ASTM D7647	>5000	94068	1341	2963		
Particles >6µm	ASTM D7647	>1300	27701	317	773		
Particles >14μm	ASTM D7647	>160	4 934	13	42		
Particles >21μm	ASTM D7647	>40	<u> </u>	5	10		
Oil Cleanliness	ISO 4406 (c)	>19/17/14	24/22/17	18/15/11	19/17/13		
PrtFilter				no image	no image		

Customer Id: TERHAM Sample No.: PC0062024 Lab Number: 02582277 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Bill Quesnel CLS,OMA II,MLA-III,LLA-I +1 (289)291-4641 x4641

Bill.Quesnel@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS Action **Status** Date Done By Description We advise that you perform a filter service, and use off-line filtration to Change Filter ? improve the cleanliness of the system fluid. Resample ? Resample in 30-45 days to monitor this situation. The air breather requires service. If unrated, we recommend that you replace with a ? **Check Breathers** suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather We advise that you check all areas where contaminants can enter the **Check Dirt Access** ? system. We advise that you perform a filter service, and use off-line filtration to Filter Fluid improve the cleanliness of the system fluid.

HISTORICAL DIAGNOSIS

06 Jul 2020 Diag: Kevin Marson

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the fluid is suitable for further service.



08 Jun 2020 Diag: Kevin Marson

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the fluid is suitable for further service.



15 Apr 2020 Diag: Kevin Marson





Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you use off-line filtration with water adsorbent filters to attempt to remove the water from this fluid. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Resample in 30-45 days to monitor this situation. All component wear rates are normal. Particles >14µm are severely high. Particles >21µm are severely high. Particles >6µm are severely high. Particles >4µm are severely high. Water contamination levels are abnormally high. Water contamination levels are abnormally high. There is a moderate concentration of water present in the fluid. Free water present. The AN level is acceptable for this fluid. The fluid is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





OIL ANALYSIS REPORT

Sample Rating


Fwd Machinery Space [450188488]

Thruster Fwd Aft - Seal Oil System (S/N Sample Tag CL-06005-S3)

Componen

Sealing System

PETRO CANADA ENERGOL GR-XP ISO 150 (65 LTR)





DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the fluid.

Fluid Condition

The AN level is acceptable for this fluid. The fluid is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.


SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PC0062024	PC	PC
Sample Date		Client Info		14 Aug 2023	06 Jul 2020	08 Jun 2020
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	NORMAL	NORMAL
	<u> </u>	and the section of	Page 21 / Page 2		for the second	la la la ma O

WEAR METAL	S	method	limit/base	current	history1	history2
PQ		ASTM D8184*		0	0	0
Iron	ppm	ASTM D5185(m)	>100	1	0	0
Chromium	ppm	ASTM D5185(m)	>3	0	0	0
Nickel	ppm	ASTM D5185(m)	>8	<1	<1	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	<1
Aluminum	ppm	ASTM D5185(m)	>3	0	0	0
Lead	ppm	ASTM D5185(m)		0	0	0
Copper	ppm	ASTM D5185(m)	>3	<1	0	<1
Tin	ppm	ASTM D5185(m)		0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	<1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		15	10	11
Barium	ppm	ASTM D5185(m)		0	0	0
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)		<1	<1	0
Calcium	ppm	ASTM D5185(m)		13	<1	<1
Phosphorus	ppm	ASTM D5185(m)		207	328	334
Zinc	ppm	ASTM D5185(m)		6	2	1
Sulfur	ppm	ASTM D5185(m)		15848	7162	7440
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTANTINIAN	ıŦO					


CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	11	<1	0
Sodium	ppm	ASTM D5185(m)		<1	<1	0
Potassium	ppm	ASTM D5185(m)	>20	<1	<1	<1

FLUID CLEANLI	NESS method	limit/base	current	history1	history2
Particles >4µm	ASTM D7647	>5000	94068	1341	2963
Particles >6μm	ASTM D7647	>1300	27701	317	773
Particles >14µm	ASTM D7647	>160	934	13	42
Particles >21µm	ASTM D7647	>40	<u> </u>	5	10
Particles >38μm	ASTM D7647	>10	1	0	0
Particles >71µm	ASTM D7647	>3	0	0	0
Oil Cleanliness	ISO 4406 (c)	>19/17/14	24/22/17	18/15/11	19/17/13





OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory Sample No. Lab Number **Unique Number**

Test Package

: PC0062024 : 02582277

: 5643342

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received : 13 Sep 2023 Diagnosed

: 19 Sep 2023 Diagnostician : Bill Quesnel

: IND 2 (Additional Tests: BottomAnalysis, FILTERPATCH, KV100, PQ, PrtCount, PrtFilter, VI)

Scotia Centre, 235 Water Strret St. John's, NL CA A1C 1B6

Suncor - Terra Nova Projects

Contact: Josh Hynes joshynes@suncor.com

> T: (709)778-3575 F: (709)724-2835

0.48

NONE

NONE

NONE

NONE

NONE

NONE

NORML

NORML

NEG

NEG

150

14.4

no image

93

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.