

PROBLEM SUMMARY


Nov5/21


Fwd Machinery Space

Thruster Aft Stbd - Steering Tube Seal (S/N Sample Tag CL-06003-S5) Component Steering

CASTROL ALPHA SP150 (35 LTR)


COMPONENT CONDITION SUMMARY





scalar

Visual*



Glycol Contamina 30 T0.25 sodium • potassium 25 20 0.15 %glycol u 15 0.10 10 0.05 0 0.00 Sep21/20 Dec6/23 May30/18 Nov5/21

RECOMMENDATION

Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend that you drain the fluid from the component if this has not already been done. Confirm the source of the lubricant being utilized for top-up/fill. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS Sample Status SEVERE SEVERE SEVERE ASTM D5185(m) >50 456 145 133 Iron ppm Chromium ASTM D5185(m) 111 28 **A** 26 ppm >15 Nickel ASTM D5185(m) >5 66 18 18 ppm Calcium ASTM D5185(m) 4 93 2 2 ppm ▲ 2 Silicon ASTM D5185(m) >15 **1**5 2 ppm Sodium ppm ASTM D5185(m) 24 8 6 0.231 Water % ASTM D6304* >0.2 0.881 ppm Water ASTM D6304* >2000 8811.5 ppm 2315 Particles >4µm ASTM D7647 >2500 • 464479 462050 507199 413927 Particles >6um ASTM D7647 >640 228181 372301 Particles >14µm ASTM D7647 >80 173818 h 21267 18887 Particles >21um ASTM D7647 >20 45497 6513 3796 Particles >38µm ASTM D7647 >4 933 99 193 Particles >71µm ASTM D7647 >3 10 5 1 26/26/21 **Oil Cleanliness** ISO 4406 (c) >18/16/13 26/26/25 26/25/22 Emulsified Water

>0.2

.2%

.5%

.5%


Customer Id: TERHAM Sample No.: PC Lab Number: 02601695 Test Package: MAR 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com



RECOMMENDED ACTIONS									
Action	Status	Date	Done By	Description					
Change Fluid			?	We recommend that you drain the fluid from the component if this has not already been done.					
Resample			?	Resample in 30-45 days to monitor this situation.					
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.					
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.					
Check Fluid Source			?	Confirm the source of the lubricant being utilized for top-up/fill.					
Check Seals			?	Check seals and/or filters for points of contaminant entry.					

HISTORICAL DIAGNOSIS

05 Nov 2021 Diag: Kevin Marson



Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend that you drain the fluid from the component if this has not already been done. We recommend an early resample to monitor this condition. Iron and nickel ppm levels are severe. Chromium ppm levels are abnormal. Particles >14µm are severely high. Particles >21µm are severely high. Particles >38µm are severely high. Particles >6µm are severely high. Particles >4µm are severely high. There is a moderate concentration of water present in the fluid. Free water present. The AN level is acceptable for this fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.



view report

21 Sep 2020 Diag: Kevin Marson





Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend that you drain the fluid from the component if this has not already been done. We recommend an early resample to monitor this condition.Iron and nickel ppm levels are severe. PQ levels are severe. Chromium ppm levels are abnormal. The very high ferrous density (PQ) index indicates that severe wear is occurring. Particles >14µm are severely high. Particles >21µm are severely high. Particles >38µm are severely high. Particles >6µm are severely high. Particles >4µm are severely high. Water Water and ppm water contamination levels are abnormal. There is a moderate concentration of water present in the fluid. The AN level is acceptable for this fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.

30 May 2018 Diag: Wes Davis



We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. Particles >6µm are severely high. Particles >4µm are severely high. Particles >14µm are abnormally high. Particles >21µm are abnormally high. The water content is negligible. The AN level is acceptable for this fluid. The condition of the fluid is suitable for further service.

view report



OIL ANALYSIS REPORT

Fwd Machinery Space Machine Id Thruster Aft Stbd - Steering Tube Seal (S/N Sample Tag CL-06003-S5) Component Steering Fluid

CASTROL ALPHA SP150 (35 LTR)

DIAGNOSIS

Recommendation

Check seals and/or filters for points of contaminant entry. We advise that you check all areas where contaminants can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend that you drain the fluid from the component if this has not already been done. Confirm the source of the lubricant being utilized for top-up/fill. Resample in 30-45 days to monitor this situation.

🛡 Wear


Chromium, iron and nickel ppm levels are severe.

Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the fluid. There is a moderate concentration of water present in the fluid. There is a moderate concentration of dirt present in the fluid. Abnormal water content and sodium(Na) level indicate possible sea water contamination. High amount of ingressed dirt has caused abrasive wear to the component.

Fluid Condition

Additive levels indicate the addition of a different brand, or type of fluid. The AN level is acceptable for this fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.



SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PC	PC0040616	PC0035660
Sample Date		Client Info		06 Dec 2023	05 Nov 2021	21 Sep 2020
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
WEAR METAL	S	method	limit/base	current	history1	history2
PQ		ASTM D8184*		98	18	e 135
Iron	ppm	ASTM D5185(m)	>50	🛑 456	145	• 133
Chromium	ppm	ASTM D5185(m)	>15	🛑 111	<u> </u>	a 26
Nickel	ppm	ASTM D5185(m)	>5	66	1 8	1 8
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		<1	<1	<1
Aluminum	ppm	ASTM D5185(m)	>5	<1	0	0
Lead	ppm	ASTM D5185(m)	>10	0	<1	0
Copper	ppm	ASTM D5185(m)	>50	3	1	1
Tin	ppm	ASTM D5185(m)	>5	0	0	0
Antimony	ppm	ASTM D5185(m)		<1	<1	<1
Vanadium	ppm	ASTM D5185(m)		0	<1	<1
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	<1	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		5	2	2
Barium	ppm	ASTM D5185(m)	4	0	0	0
Molybdenum	ppm	ASTM D5185(m)		16	4	3
Manganese	ppm	ASTM D5185(m)		9	2	2
Magnesium	ppm	ASTM D5185(m)	4	7	2	2
Calcium	ppm	ASTM D5185(m)		<mark>/</mark> 93	2	2
Phosphorus	ppm	ASTM D5185(m)	330	201	214	242
Zinc	ppm	ASTM D5185(m)	4	16	5	3
Sulfur	ppm	ASTM D5185(m)		8693	7886	8159
Lithium	ppm	ASTM D5185(m)		13	<1	<1
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	<mark>人</mark> 15	2	2
Sodium	ppm	ASTM D5185(m)		<mark>/</mark> 24	8	6
Potassium	ppm	ASTM D5185(m)	>20	2	1	<1
Water	%	ASTM D6304*	>0.2	<u> </u>		0.881
ppm Water	ppm	ASTM D6304*	>2000	A 2315		▲ 8811.5
FLUID CLEAN	INESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>2500	• 464479	462050	b 507199
Particles >6µm		ASTM D7647	>640	e 413927	228181	972301
Particles >14µm		ASTM D7647	>80	• 173818	21267	18887
Particles >21µm		ASTM D7647	>20	e 45497	6513	a 3796
Particles >38µm		ASTM D7647	>4	• 393	1 93	99
Particles >71µm		ASTM D7647	>3	<u> </u>	5	1
Oil Cleanliness		ISO 4406 (c)	>18/16/13	26/26/25	26/25/22	2 6/26/21

Contact/Location: Josh Hynes - TERHAM



491,520 122.880

€ 30,720 7 68

Ê 500

Mav30/1

Silicon (ppm)

Sep 21/20

800 Water (ppm) 6000 4000 200 n

1) 50 400

number of particles (per 1 1.92

OIL ANALYSIS REPORT

Particle Count	FLUID DEGRA		method	limit/base	current
11.520 12.880				11111/0430	
10,720 Severe	Acid Number (AN)	mg KOH/g	ASTM D974*		0.52
			method	limit/base	current
7.680 Abnormal 1.920 480 480 120 30 8	White Metal	scalar	Visual*	NONE	NONE
120-	Yellow Metal	scalar	Visual*	NONE	NONE
30-	Precipitate	scalar	Visual*	NONE	NONE
8 2 1 10 8 1 8	Silt	scalar	Visual*	NONE	NONE
0	Debris	scalar	Visual*	NONE	NONE
	Sand/Dirt	scalar	Visual*	NONE	NONE
Particle Trend	Appearance	scalar	Visual*	NORML	NORML
500k	Odor	scalar	Visual*	NORML	NORML
400k	Emulsified Water	scalar	Visual*	>0.2	.2%
300k	Free Water	scalar	Visual*		NEG
200k	FLUID PROPE	DTIES	method	limit/base	ourropt
100k					current
0k Atnormal	Visc @ 40°C	cSt	ASTM D7279(m)	150.0	155
	Visc @ 100°C	cSt	ASTM D7279(m)	14.5	13.5
May30/18 Sep21/20 Nov5/21	Viscosity Index (VI)	Scale	ASTM D2270*	95	77
Ferrous Alloys	SAMPLE IMAG	ES	method	limit/base	current
500T					
400 - irromium					-
nickel	Color				
300- E					
200					
100-	Bottom				
0	- Bottom				
May30/18 Sep 21/20 Nov5/21					
No No					
🔺 Water (KF)					
12000					
12000					

Sep21/20 : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Suncor - Terra Nova Projects Laboratory CALA Sample No. : PC Received : 07 Dec 2023 Scotia Centre, 235 Water Strret Lab Number : 02601695 Diagnosed : 09 Dec 2023 St. John`s, NL ISO 17025:2017 Accredited Laboratory : 5694780 Diagnostician : Kevin Marson CA A1C 1B6 Unique Number Test Package : MAR 2 (Additional Tests: KF, KV100, PQ, PRTCOUNT, TAN Man, VI) Contact: Josh Hynes To discuss this sample report, contact Customer Service at 1-800-268-2131. joshynes@suncor.com T: (709)778-3575 Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied. F: (709)724-2835

v5/2

Pref //33

0.38

VLITE

NONE

NONE

NONE

VLITE

NONE

NORML

▲ WGOIL

.5%

▲ >10%

142

12.6

74

0.34

NONE

NONE

NONE

VLITE

NONE

NONE

NORML

NORML

.5%

NEG

143

12.6

73