

PROBLEM SUMMARY

Sample Rating Trend

ISO

<u>Area</u>


Fwd Machinery Space [450234570]

Thruster Fwd Fore - Steering Tube Seal (S/N Sample Tag CL-06005-S5)

Component


Steering

CASTROL ALPHA SP150 (35 LTR)





COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

PROBLEMATIC TEST RESULTS									
Sample Status		SEVERE	NORMAL	SEVERE					
Particles >4µm	ASTM D7647 >250	0 98700	2254	51313					
Particles >6µm	ASTM D7647 >640	15152	232	10988					
Particles >14µm	ASTM D7647 >80	4 305	3	<u></u> 392					
Particles >21µm	ASTM D7647 >20	46	2	<u></u> 94					
Oil Cleanliness	ISO 4406 (c) >18/1	6/13 Q4/21/15	18/15/9	23/21/16					

Customer Id: TERHAM Sample No.: PC Lab Number: 02605584 Test Package: MAR 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Kevin Marson +1 (289)291-4644 x4644 Kevin.Marson@wearcheck.com

To change component or sample information: Gloria Gonzalez +1 (289)291-4643 x4643 gloria.gonzalez@wearcheck.com

RECOMMENDED ACTIONS Action **Status** Date Done By Description We advise that you perform a filter service, and use off-line filtration to Change Filter ? improve the cleanliness of the system fluid. Resample ? Resample in 30-45 days to monitor this situation. The air breather requires service. If unrated, we recommend that you replace with a ? **Check Breathers** suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather We advise that you check all areas where contaminants can enter the **Check Dirt Access** ? system. We advise that you perform a filter service, and use off-line filtration to Filter Fluid improve the cleanliness of the system fluid.

HISTORICAL DIAGNOSIS

14 Aug 2023 Diag: Bill Quesnel

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The water content is negligible. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the fluid is suitable for further service.



ISO



27 Jul 2023 Diag: Kevin Marson

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Confirm the source of the lubricant being utilized for top-up/fill. Resample in 30-45 days to monitor this situation.All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the fluid. The water content is negligible. Additive levels indicate the addition of a different brand, or type of fluid. The AN level is acceptable for this fluid. The fluid is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



05 Jun 2020 Diag: Kevin Marson

ISO



We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.All component wear rates are normal. Particles >14 μ m are severely high. Particles >21 μ m are severely high. Particles >6 μ m are severely high. The water content is negligible. The AN level is acceptable for this fluid. The condition of the fluid is suitable for further service.






OIL ANALYSIS REPORT

Fwd Machinery Space [450234570]

Thruster Fwd Fore - Steering Tube Seal (S/N Sample Tag CL-06005-S5)

Steering

CASTROL ALPHA SP150 (35 LTR)





DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the fluid.


Fluid Condition

The AN level is acceptable for this fluid. The fluid is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PC	PC0062031	PC
Sample Date		Client Info		04 Dec 2023	14 Aug 2023	27 Jul 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	NORMAL	SEVERE
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
PQ		ASTM D8184*		0	0	0
Iron	ppm	ASTM D5185(m)	>50	11	<1	5
Chromium	ppm	ASTM D5185(m)	>15	<1	0	<1
Nickel	ppm	ASTM D5185(m)	>5	<1	0	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	<1
Aluminum	ppm	ASTM D5185(m)	>5	<1	0	<1
Lead	ppm	ASTM D5185(m)	>10	<1	0	0
Copper	ppm	ASTM D5185(m)	>50	<1	<1	<1
Tin	ppm	ASTM D5185(m)	>5	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		8	6	6
Barium	ppm	ASTM D5185(m)	4	0	0	0
Molybdenum	ppm	ASTM D5185(m)		0	0	<1
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)	4	<1	<1	<1
Calcium	ppm	ASTM D5185(m)	4	14	4	8
Phosphorus	ppm	ASTM D5185(m)	330	154	191	146
Zinc	ppm	ASTM D5185(m)	4	10	6	7
Sulfur	ppm	ASTM D5185(m)		11171	12197	15922
Lithium	ppm	ASTM D5185(m)		3	<1	2
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	5	1	3
Sodium	ppm	ASTM D5185(m)		1	0	<1
Potassium	ppm	ASTM D5185(m)	>20	0	<1	<1



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited

Laboratory Sample No. Lab Number **Unique Number**

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : PC . 02605584

: 5698669

Recieved : 28 Dec 2023 Diagnosed : 02 Jan 2024 Diagnostician : Kevin Marson Test Package : MAR 2 (Additional Tests: KV100, PQ, PrtCount, VI)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Suncor - Terra Nova Projects Scotia Centre, 235 Water Strret St. John's, NL

CA A1C 1B6 Contact: Josh Hynes joshynes@suncor.com T: (709)778-3575

F: (709)724-2835