## 9970 - DIESEL ENGINE

Sample No: GFL0111778

Oil Type: PETRO CANADA DURON SHP 15W40

SAMPLE IN	IFORMAT	ION			
Sample Number		GFL0111778	GFL0063205	GFL0039077	GFL0028693
Sample Date		11 Apr 2024	06 Dec 2022	22 Dec 2021	06 Jul 2021
Machine Hours		4169	2683	1595	708
Oil Hours		550	200	600	0
Oil Changed		Changed	Changed	Changed	Changed
Sample Status		ABNORMAL	NORMAL	MARGINAL	SEVERE
OIL CONE	DITION				
Visc @ 100°C	cSt	<b>12.3</b>	<b>11.7</b>	<b>13.0</b>	<b>1</b> 0.7
Oxidation (PA)	%	80	83	31	94
CONTAM	INATION	1			
Water	%	NEG	NEG	NEG	NEG
Soot %	%	<b>1.2</b>	<b>1.1</b>	<b>0</b>	0.5
Nitration (PA)	%	120	99	38	77
Sulfation (PA)	%	65	68	40	65
Glycol	%	<b>△</b> 0.026	0.0	NEG	NEG
Fuel	%	<b>1.6</b>	<1.0	<u>^</u> 2.9	<b>6</b> .2
Silicon	ppm	<b>■</b> 9	<b>1</b> 1	<b>5</b>	<b>6</b>
Sodium	ppm	<u> </u>	<u>28</u>	■9	7
Potassium	ppm	<b>△</b> 106	□10	□0	<b>2</b>
WEAR ME	TALS				
Iron	ppm	<b>56</b>	<b>■</b> 38	<b>3</b> 1	<b>2</b> 2
Copper	ppm	<b>19</b>	<b>3</b>	<b>2</b>	<b>6</b>
Lead	ppm	<b>2</b>	<b>1</b>	<b>1</b>	<b>2</b>
Tin	ppm	<b>■</b> 0	<b>-</b> <1	<b>-</b> <1	<b>-</b> <1
Aluminum	ppm	<b>■</b> 8	<b>4</b>	<b>3</b>	<b>2</b>
Chromium	ppm	<b>3</b>	<b>2</b>	<b>2</b>	<b>2</b>
Molybdenum	ppm	<b>103</b>	<b>■</b> 58	<b>6</b> 6	<b>4</b> 7
Nickel	ppm	<b>-&lt;1</b>	<b>-</b> <1	<b>-</b> <1	<b>-</b> <1
Titanium	ppm	<b>0</b>	<u> </u>	<u> </u>	0
Silver	ppm	<b>0</b>	0	<u> </u>	<b>-</b> <1
Manganese	ppm	<b>-</b> <1	<u></u> <1	<u> </u>	<u> </u>
Vanadium	ppm	0	0	0	0
ADDITIVE	S				
Calcium	ppm	<b>945</b>	<b>1114</b>	1741	<b>9</b> 59
Magnesium	ppm	■812	910	375	<b>7</b> 93
Zinc	ppm	<b>1049</b>	<u> </u>	<b>1214</b>	■ 1023
Phosphorus	ppm	741	1034	<u></u> 1048	■893
Barium	ppm	<b>■</b> 0	<b>0</b>	<b>0</b>	<u> </u>
Boron	ppm	<u></u> 2	2	<b>1</b> 1	2
		727 (Generated: 06/09/202		_	_

**GFL Environmental - 557 - Edson** 

6615 - 4th Ave, Edson, AB CA T7E 1M5 Contact: GFL Tech wcgfldemo@gmail.com

T: F:

## Diagnosis

We advise that you check for the source of the coolant leak. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. No other corrective action is recommended at this time.All component wear rates are normal. Test for glycol is positive. Light fuel dilution occurring. There is a light concentration of glycol present in the oil. No other contaminants were detected in the oil. Viscosity of sample indicates oil is within SAE 30 range, advise investigate. The oil is no longer serviceable due to the presence of contaminants.


 Depot:
 GFL557

 Unique No:
 5773880

 Signed:
 Kevin Marson

 Report Date:
 03 May 2024

Contact/Location: GFL Tech - GFL557



Report Id: GFL557 [WCAMIS] 02632727 (Generated: 06/09/2024 17:34:52) Rev: 1

Contact/Location: GFL Tech - GFL557