


PROBLEM SUMMARY


727020-1168


Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- GAL)









RECOMMENDATION

We advise that you check the fuel injection system. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition. (Customer Sample Comment: Sampled

PROBLEMATI	C TES	T RESULT	S				
Sample Status				SEVERE	SEVERE	SEVERE	
Fuel	%	ASTM D3524	>5	37.0	● 30.1	28.9	
Visc @ 100°C	cSt	ASTM D445	15.4	7.3	▲ 8.7	<u> </u>	

Customer Id: GFL622 **Sample No.:** GFL0083930 Lab Number: 05883859 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	We recommend that you drain the oil and perform a filter service on this component if not already done.		
Change Filter			?	We recommend that you drain the oil and perform a filter service on this component if not already done.		
Resample			?	We recommend an early resample to monitor this condition.		
Check Fuel/injector System			?	We advise that you check the fuel injection system.		

HISTORICAL DIAGNOSIS

10 Mar 2023 Diag: Jonathan Hester



We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. Metal levels are typical for a new component breaking in. There is a high amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.



04 Apr 2022 Diag: Doug Bogart

FUEL



We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. Metal levels are typical for a new component breaking in. There is a high amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil.






OIL ANALYSIS REPORT

727020-1168

Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- GAL)



DIAGNOSIS

Recommendation

We advise that you check the fuel injection system. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition. (Customer Sample Comment: Sampled

Wear

Metal levels are typical for a new component breaking in.

Contamination

There is a high amount of fuel present in the oil.

▲ Fluid Condition

Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.

J. (12)	April022 Mar2023 Jun2023							
SAMPLE INFOR	MATION	method	limit/base	current	history 1	history 2		
Sample Number		Client Info		GFL0083930	GFL0071392	GFL0042773		
Sample Date		Client Info		21 Jun 2023	10 Mar 2023	04 Apr 2022		
Machine Age	hrs	Client Info		148621	14694	142824		
Oil Age	hrs	Client Info		0	0	10000		
Oil Changed		Client Info		Not Changd	Changed	Changed		
Sample Status				SEVERE	SEVERE	SEVERE		
CONTAMINAT	ION	method	limit/base	current	history 1	history 2		
Glycol		WC Method		NEG	NEG	NEG		
WEAR METAL	.S	method	limit/base	current	history 1	history 2		
Iron	ppm	ASTM D5185m	>100	12	13	26		
Chromium	ppm	ASTM D5185m	>20	0	1	1		
Nickel	ppm	ASTM D5185m	>4	0	0	0		
Titanium	ppm	ASTM D5185m		0	<1	<1		
Silver	ppm	ASTM D5185m	>3	0	0	0		
Aluminum	ppm	ASTM D5185m	>20	3	2	2		
Lead	ppm	ASTM D5185m	>40	<1	2	6		
Copper	ppm	ASTM D5185m	>330	<1	1	2		
Tin	ppm	ASTM D5185m	>15	0	<1	<1		
Vanadium	ppm	ASTM D5185m		0	<1	0		
Cadmium	ppm	ASTM D5185m		0	0	0		
ADDITIVES		method	limit/base	current	history 1	history 2		
Boron	ppm	ASTM D5185m	0	7	48	69		
Barium	ppm	ASTM D5185m	0	4	0	0		
Molybdenum	ppm	ASTM D5185m	60	36	48	45		
Manganese	ppm	ASTM D5185m	0	0	1	<1		
Magnesium	ppm	ASTM D5185m	1010	531	756	231		
Calcium	ppm	ASTM D5185m	1070	630	624	572		
Phosphorus	ppm	ASTM D5185m	1150	583	672	274		
Zinc	ppm	ASTM D5185m	1270	726	862	345		
Sulfur	ppm	ASTM D5185m	2060	2079	2437	796		
CONTAMINAN	ITS	method	limit/base	current	history 1	history 2		
Silicon	ppm	ASTM D5185m	>25	4	9	5		
Sodium	ppm	ASTM D5185m		1	3	1		
Potassium	ppm	ASTM D5185m	>20	<1	1	3		
Fuel	%	ASTM D3524		37.0	30.1	28.9		
INFRA-RED		method	limit/base	current	history 1	history 2		
Soot %	%	*ASTM D7844	>3	0.7	0.5	1.6		
Nitration	Abs/cm	*ASTM D7624		11.4	11.6	16.5		
Sulfation	Abs/.1mm	*ASTM D7415	>30	20.4	20.6	28.1		
FLUID DEGRAI	OITAC	method	limit/base	current	history 1	history 2		
Oxidation	Abs/.1mm	*ASTM D7414	>25	20.3	20.6	31.0		
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	9.0	9.4	8.7		



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number **Unique Number**

: 05883859 : 10534342

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : GFL0083930 Received : 26 Jun 2023

Diagnosed

: 29 Jun 2023 Diagnostician : Don Baldridge

Traverse City, MI US 49686 Contact: GARY BREWER

GFL Environmental - 622 - Traverse City Hauling

Test Package : FLEET (Additional Tests: PercentFuel) Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Submitted By: TECHNICIAN ACCOUNT

T: F:

160 Hughes Dr